U.S. Army Corps of Engineers Alaska District



FIRST PERIODIC REVIEW REPORT

SITE 7 CARGO BEACH ROAD LANDFILL NORTHEAST CAPE FUDS ST. LAWRENCE ISLAND, ALASKA

Formerly Used Defense Site No. F10AK0969-05

FINAL FEBRUARY 2015

U.S. Army Corps of Engineers Alaska District



SITE 7 CARGO BEACH ROAD LANDFILL FIRST PERIODIC REVIEW REPORT

NORTHEAST CAPE FUDS ST. LAWRENCE ISLAND, ALASKA

Formerly Used Defense Site No. F10AK0969-05

FINAL FEBRUARY 2015

APPROVED BY:	DATE:
Christopher D. Lestochi	
Colonel, Corps of Engineers	

District Commander

F10AK096905_07.11_0506_p 200-1f

TABLE OF CONTENTS

<u>SEC</u>	TIO	<u>N</u>		PAGE
ACR	RONY	MS AN	ID ABBREVIATIONS	v
EXE	CUT	IVE SU	MMARY	ES-1
PER	IODI	C REVI	EW SUMMARY FORM	S-1
1.0	INT	RODUC	CTION	1-1
	1.1	PUR	POSE OF THIS REVIEW	1-1
	1.2	RES	PONSIBILITIES	1-1
	1.3	OVE	RVIEW	1-2
2.0	SITI	E CHRC	NOLOGY	2-1
3.0	BAC	CKGRO	UND	3-1
	3.1	NOR	THEAST CAPE	3-1
		3.1.1	Physical Characteristics	3-1
		3.1.2	Geology	3-2
		3.1.3	Land and Resource Use	3-3
	3.2	NOR	THEAST CAPE SITE HISTORY	3-3
		3.2.1	History of Contamination	3-4
		3.2.2	Initial Response	3-6
		3.2.3	Basis for Taking Action	3-7
4.0	SITI	E 7 REM	MEDIAL ACTIONS	4-1
	4.1	REM	IEDY SELECTION	4-1
		4.1.1	Removal Action Objectives	4-1
		4.1.2	Selected Remedy	4-2
	4.2	REM	IEDY IMPLEMENTATION	4-4
		4.2.1	Remedy Implementation and Status	4-4
		4.2.2	Operations and Maintenance	4-6
5.0	PRC	GRESS	SINCE THE LAST REVIEW	5-1
6.0	PER	IODIC	REVIEW PROCESS	6-1
	6.1		MINISTRATIVE COMPONENTS OF THE PERIODIC REVIEW CESS	6-1
	6.2	COM	MUNITY NOTIFICATION AND INVOLVEMENT	6-1
	6.3	DOC	CUMENT REVIEW	6-2

TABLE OF CONTENTS (Continued)

SECTIO	\underline{NN}	PAGE
6.4	DATA REVIEW	6-3
6.5	RECOVERED PRODUCT WASTE CHARACTERIZATION	6-4
6.6	SURFACE WATER	6-5
6.7	GROUNDWATER	6-6
6.8	RECOMMENDATIONS FOR SITE 7	6-6
6.9	INTERVIEWS	6-7
7.0 TE	CHNICAL ASSESSMENT	7-1
7.1	QUESTION A	7-1
7.2	QUESTION B	7-2
7.3	QUESTION C	7-4
7.4	TECHNICAL ASSESSMENT SUMMARY	7-4
8.0 ISS	UES	8-1
8.1	COMMUNITY ISSUES	8-2
9.0 RE	COMMENDATIONS AND FOLLOW-UP ACTIONS	9-1
10.0 PR	OTECTIVENESS STATEMENT(S)	10-1
11.0 NE	XT REVIEW	11-1
12.0 RE	FERENCES	12-1
	TABLES	
Table 2-1	Chronology of Site Events	2-1
Table 4-1	Northeast Cape Cleanup Levels	4-2
Table 4-2	Site 7 Selected Remedies and Current Status	4-3
Table 6-1	Site 7 Maximum Detected Concentrations in Excavated Soil	6-5
Table 8-1	Issues Identified	8-1
Table 9-1	Recommendations and Follow-up Actions	9-1

TABLE OF CONTENTS (Continued)

SECTION		<u>PAGE</u>
	APPENDICES	
Appendix A	Figures	
Appendix B	Cleanup Levels, Toxicity, and Risk Evaluation	
Appendix C	Site Inspection Checklists and Logbook	
Appendix D	Photograph Log	
Appendix E	Completed Interview Questionnaire Forms	

Appendix F Public Notice Documentation

(intentionally blank)

ACRONYMS AND ABBREVIATIONS

°F degrees Fahrenheit

AAC Alaska Administrative Code

AC&WS Aircraft Control and Warning Station
ACAT Alaska Community Action on Toxics

ADEC Alaska Department of Environmental Conservation ARAR applicable or relevant and appropriate requirements

bgs below ground surface

Bristol Bristol Environmental Remediation Services, LLC

BTEX benzene, toluene, ethylbenzene, and xylenes

CERCLA Comprehensive Environmental Response, Compensation, and Liability Act

COC contaminant of concern

CON/HTRW containerized hazardous, toxic, or radioactive wastes

COPC contaminant of potential concern

DD decision document

DHHS U.S. Department of Health and Human Services

DRO diesel-range organics

EPA U.S. Environmental Protection Agency

FUDS Formerly Used Defense Site GRO gasoline-range organics

HWAP hazardous waste accumulation point

Jacobs Engineering Group Inc.

LUC land use controls

mg/kg milligrams per kilogram mg/L milligrams per liter

MOC Main Operations Complex

PAH polycyclic aromatic hydrocarbon

PCB polychlorinated biphenyl
POL petroleum, oil, and lubricants
RAB Restoration Advisory Board
RAO removal action objective

RCRA Resource Conservation and Recovery Act

RecKey record key

RI remedial investigation
ROD Record of Decision
RRO residual-range organics
TAH total aromatic hydrocarbon

ACRONYMS AND ABBREVIATIONS (Continued)

TAqH total aqueous hydrocarbon

TBC to be considered

USACE U.S. Army Corps of Engineers

WACS White Alice Communications System

EXECUTIVE SUMMARY

The U.S. Army Corps of Engineers contracted Jacobs Engineering Group Inc. to conduct the

first Periodic Review of the selected remedy for Site 7 Cargo Beach Road Landfill (Site 7) at

the Northeast Cape Formerly Used Defense Site on St. Lawrence Island, Alaska, in

September 2013. This Report presents the results of the review.

The purpose of this review is to ensure the remedy selected in *Decision Document: Site* 7

Cargo Beach Road Landfill, Containerized Hazardous, Toxic, and Radioactive Waste

(CON/HTRW) Project #F10AK0969-05 (USACE 2009a), signed 19 June 2009, has been put

into action, is performing effectively, and continues to be protective of human health and the

environment. Data considered during this review included sample results and site inspections

available as of April 2014. The Summary Form on the following pages presents the issues that

were identified during the review, associated recommendations, follow-up actions, and the

protectiveness statement.

Overall, this Periodic Review found the selected remedy for Site 7 will be protective when

remedy implementation is complete.

ES-1

(intentionally blank)

FINAL

PERIODIC REVIEW SUMMARY FORM

SITE IDENTIFICATION

Site Name: Site 7 Cargo Beach Road Landfill, Northeast Cape (St. Lawrence Island)

FUDS ID: F10AK0969-05

EPA ID: AK9799F2999

Region: 10 **State:** Alaska **City/County:** St. Lawrence Island

SITE STATUS

NPL Status: Non-NPL Site

Multiple OUs? No Has the site achieved construction completion? No

REVIEW STATUS

Lead agency: Other Federal Agency

If "Other Federal Agency" was selected above, enter Agency name: USACE

Author name (Federal or State Project Manager):

Jacobs Engineering Group Inc.

on behalf of USACE, Alaska District

Federal Project Manager Valerie Palmer

Author affiliation: Contractor

Review period: September 2009 – April 2014

Date of site inspection: 13 September 2013 – 15 September 2013

Type of review: Periodic Review

Review number: 1 (one)

Triggering action date: 19 June 2009

Due date (five years after triggering action date): 19 June 2014

		ISSU	ES/RECOMMEND	ATION	IS .	
Site: 7 Issue Category: Remedy Completion						
	Issue: Land use controls to limit groundwater use and prevent construction of buildings on top of the landfill are not implemented.					
	Recommendation: Implement LUCs following completion of the remedial action field work as described in the DD.					
Affect Current Protectiveness	Affect Fu Protectiv		Implementing Party	Regula Party	ntory	Milestone Date
No	Yes		USACE	ADEC		2018
Site: 7	Issue Cat	tegory:]	Remedy Implementa	ition		
	Issue: Th cap.	e 2013 s	site inspection identi	fied deb	ris protrudi	ng from the landfill
	Recomm	endatio	n: Remove debris pr	otruding	from the l	andfill cap.
Affect Current Protectiveness	Affect Fu Protectiv		Implementing Party	Regula Party	ntory	Milestone Date
No	No		USACE	ADEC		2018
Site: 7 Issue Category: Remedy Implementation						
	Issue: The 2013 site inspection identified metal and wood debris in and around ponds adjacent to the landfill cap.					
Recommendation: Remove debris identified in and around ponds to the landfill cap.			and ponds adjacent			
Affect Current Protectiveness	Affect Future Protectiveness		Implementing Party	Regulatory Party		Milestone Date
No	No		USACE	ADEC		2018
PROTECTIVENESS STATEMENT						
ε					Addendum Due Date (if applicable):	
<i>Protectiveness Statement:</i> The remedy at Site 7 is expected to be protective of human health and the environment upon completion. In the interim, no exposure pathways that could result in unacceptable risks have been noted.						

1.0 INTRODUCTION

The U.S. Army Corps of Engineers (USACE) contracted Jacobs Engineering Group

Inc. (Jacobs) to conduct the first Periodic Review of the selected remedy at Site 7 Cargo

Beach Road Landfill (Site 7) at Northeast Cape on St. Lawrence Island, Alaska (Figure A-1),

in September 2013.

1.1 PURPOSE OF THIS REVIEW

The purpose of this Periodic Review is twofold: to evaluate the implementation and

performance of the remedial action that was selected for Site 7 and to determine if this action

is protective of human health and the environment. The methods, findings, and conclusions of

this Periodic Review identify issues found through an examination of the data collected over

the past five years and provide recommendations to address them. This is the first Periodic

Review for Site 7.

The Periodic Review process for Site 7 was triggered by the signing of *Decision Document*:

Site 7 Cargo Beach Road Landfill, CON/HTRW Project #F10AK0969-05 (USACE 2009a),

19 June 2009.

1.2 **RESPONSIBILITIES**

USACE, Alaska District, is the lead agency for remedial actions at Site 7, located within the

Northeast Cape Formerly Used Defense Site (FUDS). USACE contracted Jacobs to conduct

and prepare this Periodic Review Report. The selected final remedial actions for Site 7 were

chosen in accordance with the Defense Environmental Restoration Program, United States

Code, Title 10, Section 2701, et seq.

Per FUDS Program Policy ER 200-3-1 (USACE 2004a), containerized hazardous, toxic, or

radioactive wastes projects involving tanks, transformers, and other containers generally are

not regulated under the Comprehensive Environmental Response, Compensation, and

Liability Act (CERCLA) process. However, this project has followed the CERCLA process as

1-1

a matter of administrative consistency to foster community trust and preserve good public relations with an ongoing project at the same location (USACE 2009a).

The primary concern at Site 7 is drums and other containers containing petroleum, oil, and lubricants (POL). However, with any unpermitted dump site, there is the potential for unknown hazardous wastes to be discovered. If an actual or threatened release of a CERCLA hazardous substance, pollutant, and/or contaminant is identified during the performance of this CON/HTRW cleanup, the situation will need to be assessed to determine if the project needs to transition to a CERCLA response action. An evaluation will be made, in accordance with CERCLA and the National Contingency Plan, to determine if a removal action is warranted to protect human health and the environment.

1.3 OVERVIEW

The Periodic Review was conducted with all data available in the information repositories as of February 2014. The project team consisted of the USACE project manager, technical representatives, and contracted environmental engineering support. This effort included a review of the decision document (DD) requirements and work that has been done to satisfy those requirements, current and past monitoring data, and the current status of the remedy and the physical condition of the site. The general public was notified of the review with public notices placed in the *Nome Nugget* on 18 and 19 August 2013. In addition, a flyer containing the same information was mailed to community members and Alaska Department of Environmental Conservation (ADEC) in September 2013. Site 7 was visited and a site inspection was performed on 13 September 2013.

2.0 SITE CHRONOLOGY

Important events and relevant dates for Northeast Cape are shown in Table 2-1.

Table 2-1 Chronology of Site Events

Event	Date
Northeast Cape site acquired by the U.S. Air Force	1952
Aircraft Control and Warning Station constructed	1951-1952
WACS constructed	1954
Aircraft Control and Warning Station operations terminated	1969
WACS operations terminated	1972
Bureau of Land Management obtained ownership of Northeast Cape	August 1975
Alaska Native Claims Settlement Act transferred land ownership to Sivuqaq, Inc. and Kukulget, Inc.	June 1979
Environmental Assessment conducted	1985
Site Assessment conducted	1991 and 1992
Phase I RI conducted	1994
All electrical transformers removed	1994
Phase II RI/Feasibility Study and Human Health and Ecological Risk Assessment drafted	1996
Remedial Action conducted to remove communications wire and cable on the tundra	1997
Phase II RI/Feasibility Study finalized	September 1998
Site Assessment conducted	1999
Debris, hazardous waste, aboveground storage tank, and fuel pipeline removed	2000
Underground storage tanks, PCB- and POL-contaminated soil removed, buildings demolished	2001
Phase III Remedial Investigation conducted	2001 – 2002
30 buildings and utilidor demolished; drums, communication poles, and wire removed	2003
Human Health and Environmental Risk Assessment finalized	2004
Feasibility Study prepared	2007
Groundwater Use Determination (18 AAC 350) submitted to ADEC	April 2007
ADEC comments on the Northeast Cape 350 Determination received (ADEC 2007b)	May 2007

Table 2-1 Chronology of Site Events (Continued)

Event	Date
DD selecting remedy for Sites 1 through 6 and 8 through 34 approved by HQ USACE	September 2009
DD selecting remedy for Site 7 approved by USACE-POA	June 2009
Remedial action begun to implement remedy for Site 7	June 2009
Bristol requested landfill closure by ADEC for Site 7	November 2009
Site 7 Landfill Cap Construction Report prepared	May 2010
EPA evaluated USACE Cleanup of FUDS at Northeast Cape and Gambell	February 2013
Public notice of Five-Year Review published and public comment period opened	August 2013
Five-Year Review site visit	September 2013
Public comment period closed	February 2014

 $\underline{\textbf{Note:}}$ For definitions, see the Acronyms and Abbreviations section.

3.0 BACKGROUND

This is the first Periodic Review for Site 7. The section below is intended to describe the general conditions of the Northeast Cape Site in its entirety; the individual Site 7 history, physical characteristics, and land uses are discussed in detail in Section 3.2.1.

3.1 NORTHEAST CAPE

The project number for Site 7, located within the Northeast Cape FUDS is F10AK0969-05. The ADEC contaminated sites record key (RecKey) number for the entire Northeast Cape Site is 198532X917901. Site 7 is tracked with a separate RecKey (198532X917907) and File Number (475.38.013). The ADEC Hazard ID number for Site 7 is 213. The Environmental Protection Agency (EPA) site identification number for Northeast Cape is AK9799F2999. The Northeast Cape FUDS is not listed on the National Priorities List.

3.1.1 Physical Characteristics

The Northeast Cape FUDS is located on St. Lawrence Island, Alaska, in the western portion of the Bering Sea, approximately 135 air-miles southwest of Nome (Figure A-1). It is 9 miles west of the northeastern cape of St. Lawrence Island at 63°19' north, 168°58' west. The Northeast Cape property originally encompassed approximately 4,800 acres (7.5 square miles) and is bounded by Kitnagak Bay to the northeast, Kangighsak Point to the northwest, and the Kinipaghulghat Mountains to the south.

The Northeast Cape FUDS consists mainly of rolling tundra, which rises from the Bering Sea toward the base of the Kinipaghulghat Mountains. These mountains rise abruptly to an elevation of approximately 1,800 feet above sea level roughly 3 miles from the coastline. The Northeast Cape FUDS is not connected to other permanent communities on the island by road and is only accessible by air, water, or all-terrain vehicle trails. The Village of Savoonga, the closest community, is located approximately 60 miles to the northwest (Figure A-1). Savoonga has a subarctic maritime climate with some continental influences during the winter. Summer temperatures average between 40 to 51 degrees Fahrenheit (°F) and winter

temperatures average between -7 to 11 °F. Temperature extremes have been recorded at -34 and 67 °F. Average annual precipitation is 10 inches, with 58 inches of snowfall. The island is subject to prevailing winds, averaging 18 miles per hour.

3.1.2 Geology

As presented in the DDs (USACE 2009a, b), St. Lawrence Island consists of isolated bedrock highlands of igneous, metamorphic, and older sedimentary rocks surrounded by unconsolidated surficial deposits overlying a relatively shallow erosional bedrock surface. The main area of operation, known as the Main Operations Complex (MOC), is located at an elevation of approximately 100 feet. In the area of the MOC, shallow, unconsolidated surficial materials overlie quartz monzonitic rocks of the Kinipaghulghat Pluton (Patton and Csejtey 1980). The pluton forms the mountainous area south of the Northeast Cape FUDS, which includes Kangukhsam Mountain. The Suqitughneq River drainage in the Kinipaghulghat Pluton has created an erosional valley and alluvial fan of unconsolidated sediments. The Northeast Cape FUDS is located on this alluvial fan, which protrudes north from the mountain front toward the Bering Sea. Granitic bedrock materials are exposed at the coast north of the site at Kitnagak Bay, which suggests the quartz monzonitic bedrock underlies the unconsolidated materials at a relatively shallow depth on a wave-cut erosional platform.

In general, the native soil stratigraphy at Northeast Cape is characterized by silts near the surface, overlying more sand-dominated soils at depth. The silt contains varying quantities of clay/sand/gravel, and varies from 0 to 10 feet in thickness. The silt is dark brown to dark green and sometimes exhibits a mottled texture. In some areas, the silt exhibits an aqua-green or blue color. Dark brown silts are observed in outcrops. The sand at depth contains varying degrees of silt/gravel/cobbles that range from 2 feet to greater than 20 feet in thickness. These deeper, coarse-grained materials generally are unsorted and likely to be of glaciofluvial origin. The depth to bedrock at the Northeast Cape FUDS is unknown (USACE 2009a, b).

3.1.3 Land and Resource Use

St. Lawrence Island residents from the villages of Gambell and Savoonga engage in

subsistence fishing, hunting, and gathering in the Northeast Cape FUDS area year-round.

Currently, there are not any permanent residents of the Northeast Cape area; however,

representatives of the Native Village of Savoonga have indicated a desire to re-establish a

permanent residential community at the site in the future.

St. Lawrence Island supports habitats for the following endangered or threatened species: the

polar bear (threatened); spectacled eider (endangered); Steller's eider (threatened); and the

Western Distinct Population Segment of Steller sea lion (endangered). Walrus are protected

under the Marine Mammal Protection Act. The area of Northeast Cape FUDS is used for the

collection of berries and subsistence hunting of reindeer. The Sugitughneq River, which is

located within the Northeast Cape FUDS, is used for subsistence fishing. The ocean

surrounding the Northeast Cape FUDS is used extensively for subsistence activities, including

fishing and hunting of whales, walrus, seals, and sea birds.

3.2 NORTHEAST CAPE SITE HISTORY

The Northeast Cape FUDS was constructed as an Aircraft Control and Warning Station

(AC&WS) during 1950 and 1951 to provide radar coverage and surveillance for the Alaskan

Air Command, and later for the North American Air Defense Command, as part of the Alaska

Early Warning System. The site was activated in 1952 and a White Alice Communications

System (WACS) station was added to the site in 1954. The AC&WS and WACS operations

supported 212 personnel and were terminated in 1969 and 1972, respectively. The majority of

military personnel were removed from the site by the end of 1969.

The Northeast Cape site included areas for housing site personnel, power plant facilities, fuel

storage tanks, distribution lines, maintenance shops, wastewater treatment facilities, and

landfills. The buildings and majority of furnishings and equipment related to the AC&WS

were abandoned in place initially due to the high cost of off-island transport.

3-3

In 1971, the villages of Gambell and Savoonga opted out of the Alaska Native Claims Settlement Act, which allowed for title to 1.136 million acres of land in the former St. Lawrence Island Reindeer Reserve established in 1903. The Gambell Native Corporation and Savoonga Native Corporation (now known as Sivuqaq, Inc. and Kukulget, Inc., respectively) received titles to all of St. Lawrence Island (except U.S. Surveys 4235, 4237, 4340, 4369, 3728) by Interim Conveyance No. 203 dated 21 June 1979. In 1982, the Navy obtained approximately 26 acres of land containing the former WACS. The land transfer later was deemed invalid and property ownership was reverted to Sivuqaq, Inc., and Kukulget, Inc.

3.2.1 History of Contamination

Environmental investigations at Northeast Cape FUDS began in the mid-1980s, and subsequent phased remedial investigations (RI) were conducted between 1994 and 2004. The studies divided the concerns at Northeast Cape among 34 separate sites (USACE 2009a, b). One of these sites, Site 7, is an unpermitted landfill that was used as the installation's primary solid waste disposal area from 1965 until closure in 1974. Site 7 is located 0.8 miles south of Cargo Beach, midway between the MOC and the beach at Kitnagak Bay. The dump contains a variety of unknown materials. The landfill appears to have been created by dumping debris off the sides of a topographic mound. The debris then was covered by grading soil out from the top of the mound.

Environmental sampling activities at Site 7 have included the collection of soil, sediment, surface, and shallow groundwater samples. Detected analytes were compared to background concentration and the most conservative ADEC Method Two cleanup levels to determine the contaminants of concern (COC) (USACE 2009a). Chemical analyses were conducted for petroleum-related compounds, volatile organic compounds, semivolatile organic compounds, metals, pesticides, and polychlorinated biphenyls (PCB). Based on the results of the phased RIs, contaminants exceeding action levels in soil were identified in a limited amount of soil and included diesel-range organics (DRO), residual-range organics (RRO), PCBs, arsenic, chromium, and lead.

In soil, the maximum DRO concentration was detected approximately 75 feet east of Cargo Beach Road at a concentration of 32,000 milligrams per kilogram (mg/kg) (USACE 2009a). At all other sampling locations, DRO concentrations ranged from nondetect to 2,300 mg/kg, which is below the site-specific cleanup level of 9,200 mg/kg. PCBs were detected in soil along the southeastern edge of the landfill at concentrations ranging from nondetect to 50.8 mg/kg (USACE 2009a). In 2005, six locations with PCBs concentrations greater than 1 mg/kg were excavated and disposed offsite. Confirmation sampling results demonstrated that PCBs were successfully removed to concentrations below 1 mg/kg at four of the six locations. Two locations (7A and 7E), located on the southeastern slope of the landfill, still may contain PCB concentrations greater than 1 mg/kg between 2 and 3.5 feet below ground surface (bgs).

In sediment, chromium and PCBs were detected above cleanup levels at one location (SD301) with concentrations of 100 mg/kg and 1.78 mg/kg, respectively (USACE 2009a). DRO were detected at location SD301 at a maximum concentration of 4,900 mg/kg (USACE 2009a). In surface water, DRO were detected in one sample (SW101) northeast of the landfill in 1994 with an average triplicate concentration of 8.9 milligrams per liter (mg/L). No other exceedances were detected in surface water in 1994.

During the Phase I RI in 1994, four boreholes were placed around the landfill in an attempt to locate groundwater and characterize migration of contaminants around the landfill. Boreholes were drilled to a maximum depth of 31 feet and one borehole was terminated at 15 feet bgs and converted to monitoring well MW7-4 located east of the landfill and adjacent to a pond (USACE 2009a). Groundwater was not encountered at the other three boreholes. The lack of groundwater in these boreholes was attributed to frozen soil conditions. A thin layer of perched groundwater may be present immediately above the frozen soil during the warmer summer months (USACE 2009a). In 2001, several temporary well points were advanced in the areas surrounding the landfill. These well points generally confirmed the lack of groundwater. One location (WP7-1), located west of the landfill, contained anomalous levels of several metals, including arsenic, chromium, and lead, as well as low levels of DRO and RRO. The water samples were not filtered and turbid, suggesting the metals detected were

likely originating from the suspended sediments in the water column and are not representative of dissolved phase shallow groundwater conditions at the site. Groundwater also was collected from temporary well point WP7-3, which did not identify contaminants greater than cleanup levels (USACE 2009a). Groundwater migration from the site likely is limited because of the low permeability of the shallow, partially frozen soils. Groundwater probably remains in a relatively localized area with any migration occurring in a northeasterly direction, corresponding to surface topography.

Sampling of shallow groundwater is problematic at Site 7 due to the tundra/wetland environment, and sample collection is difficult because water is intermittent, slow to recharge, and highly turbid. Groundwater exposure at Site 7 is incomplete because there is not a sufficient quantity of water produced to be considered a reasonable potential future source for drinking water.

3.2.2 Initial Response

Several non-time-critical interim removal actions were performed throughout Northeast Cape to address the removal of containerized hazardous/toxic waste items, buildings and miscellaneous debris, and hotspots of contaminated soils (USACE 2009a). Remedial actions specific to Site 7 are as follows:

- In 2000, more than 6,000 55-gallon drums were removed from the surrounding area.
- In 2003, 15 tons of scrap metal were removed from the area east of Cargo Beach Road.
- In 2005, approximately 14 tons of PCB-contaminated soil from six areas along the southeastern edge of the landfill, as well as exposed drums and miscellaneous debris from the landfill perimeter edges were removed (USACE 2009a).
- In 2007, a geophysical survey (USACE 2007a) was conducted to map the extent of buried
 metallic anomalies. The geophysical data were consistent with side-cast debris around the
 edges of a natural topographic mound. Most of the remaining debris identified was located
 at the northwest and southeast edges of the topographic mound. Buried debris was not
 identified to extend beneath Cargo Beach Road.

3.2.3 Basis for Taking Action

The response actions selected in the DD are necessary to protect the public health and welfare or the environment from actual or threatened releases of hazardous substances into the environment, including unknown liquid contents of buried and partially exposed drums (USACE 2009a).

(intentionally blank)

4.0 SITE 7 REMEDIAL ACTIONS

Removal action objectives (RAO) and the selected remedy are presented in this section. Details regarding the initial plans, remedy implementation, and current status of the remedy are provided.

4.1 REMEDY SELECTION

The DD addressing Site 7 was approved on 19 June 2009 (USACE 2009a). The goal of the Defense Environmental Restoration FUDS Program is to reduce the risk resulting from past military activities to safe levels, in a timely, cost-effective manner.

4.1.1 Removal Action Objectives

Specific response action alternatives were developed and evaluated for Site 7. The RAOs for Site 7 are as follows:

- Reduce threats to human health, safety, and the environment.
- Remove drums containing POL, hazardous substances, pollutants, or contaminants, as necessary, to reduce the likelihood of future spillage, leakage, and exposure to humans, animals, and the food chain.
- Prevent current and future exposure to humans by ingestion, inhalation, and dermal contact with contaminated soils at levels above risk-based cleanup levels.
- Prevent exposure to ecological receptors by direct contact with contaminated soils/sediment above risk-based cleanup levels.

Cleanup levels for identified COCs in various media at Site 7 established in the DD are presented in Table 4-1. Soil cleanup levels were developed based on the Human Health and Ecological Risk Assessment (USACE 2004b) to be protective of future permanent residents with an assumed lifetime exposure to contaminated soils through incidental ingestion, inhalation, or dermal contact. Sediments that are intermittently submerged (i.e., ephemeral ponds, wet tundra) are considered soil, including all areas adjacent to Site 7. Surface water must meet water quality standards promulgated by the State of Alaska under Title 18 of the Alaska Administrative Code (AAC), Section 70 (18 AAC 70). The water quality criteria for

petroleum hydrocarbons, oil, and grease are described in 18 AAC 70.020(b) and stipulate these compounds may not cause a visible sheen upon the surface of the water. In addition, the regulations provide acceptable levels for total aromatic hydrocarbons (TAH) and total aqueous hydrocarbons (TAqH).

Table 4-1
Northeast Cape Cleanup Levels

Contaminant of Concern	Soil (mg/kg)	Surface Water (mg/L)
Arsenic	11 ^a	
PCBs	1 ^b	
DRO	9,200 ^c	no sheen
GRO		no sheen
RRO	9,200 ^c	no sheen
TAH ¹		0.010
TAqH ²		0.015

Notes:

4.1.2 Selected Remedy

Response action alternatives considered for Site 7 included: no further action; land use controls (LUC); natural attenuation; long-term monitoring; capping; and excavation and offsite disposal (USACE 2009a). Alternatives were evaluated for their ability to provide overall protection of human health and the environment; compliance with risk-based standards; short- and long-term effectiveness and performance; reduction in toxicity, mobility, and volume; implementability; and cost (USACE 2009a). The selected remedy for Site 7 contains several components and includes capping with intrusive removal action and incidental removal of contaminated soil. The selected remedial components for Site 7 and their current status are presented in Table 4-2.

⁻⁻ Cleanup level not specified in the DDs (USACE 2009b)

¹TAH is the sum of BTEX.

² TAqH is the sum of BTEX and PAH.

^a Site-specific background value

^b 18 AAC 75, Table B1, over 40 inch Zone, direct contact pathway (as updated 9 October 2008)

^cRisk-based cleanup level derived from site-specific risk assessment, ingestion/inhalation pathways, future residential use (USACE 2009b).

Table 4-2
Site 7 Selected Remedies and Current Status

Remedial Component	Status	
Expose underlying drums/debris by disturbing the upper approximately 1 foot of fill across the areas with mapped metallic anomalies (estimated 150,000 square feet) to determine if near-surface drums are present.	Completed in 2009. Ten test pits (10 feet by 10 feet by 4 feet) and 72 shallow potholes were advanced at Site 7 (USACE 2010a).	
Excavate test pits or trenches distributed across the areas of known metallic anomalies to determine if large caches of drums are present.	Completed in 2009. Excavation during drum removal overlapped the areas with magnetic anomalies (129,000 square feet). Final excavation depth was not reported (USACE 2010a).	
Remove or drain identified drums with liquid content; characterize the waste contents; transport offsite for proper disposal.	Completed in 2009. 182 drums located in the test pits and potholes were drained, cleaned, and crushed before burial under the landfill cap. Drum contents were comingled and sent to an offsite disposal facility (USACE 2010a).	
Remove incidental contaminated soils associated with identified drums to the extent grossly stained soils are determined by the contractor and USACE Quality Assurance Representative; characterize the soil for disposal; transport offsite for proper disposal.	Completed in 2009. 100 tons of soil was removed from 1 to 2 feet below the drums during excavation and sent to an offsite disposal facility (USACE 2010a).	
Cap the debris with a minimum 2 feet of fill.	Completed in 2009. Landfill cap material (28,994 cubic yards) was transported to the site from a local borrow source and spread across the site USACE 2010a).	
Re-vegetate the site.	Initiated in 2009 (USACE 2010a).	
Survey the landfill boundary with map and text description.	Completed in 2009 (USACE 2010a).	
Deed notation	Not yet completed.	
Implement LUCs to limit groundwater use and prevent construction of buildings on top of the landfill.	LUCs to limit groundwater use and prevent construction of buildings on top of the landfill have not been implemented.	
Visual monitoring of the cap for settlement and	Ongoing.	
erosion over a period of 5 years, with additional periodic reviews as necessary.	Conducted in 2011, 2012, and 2013 (Craner 2011; Shewman 2012; Geist 2013).	

4.2 REMEDY IMPLEMENTATION

This section presents a brief description of the selected remedy, its implementation history, current status, and operations and maintenance plan.

4.2.1 Remedy Implementation and Status

The DD-selected remedy for Site 7 was to excavate test pits across the areas of known metallic anomalies to expose underlying drums and debris, remove or drain near-surface drums, install a landfill cap, conduct periodic visual monitoring for settlement and erosion over a period of five years, survey the landfill boundary, and implement LUCs to limit groundwater use and prevent construction of buildings on top of the landfill.

Remedy implementation was initiated in 2009. Metallic anomalies identified by geophysical investigation in 2007 were located by survey and investigated. The top 1 foot of soil was uncovered to locate drums within the shallow subsurface. Excavations included 73 shallow "potholes" across the surface of the landfill, 10 test pits (at least an area of 100 square feet and a depth of 4 feet), and previously delineated magnetic anomaly areas covering approximately 129,000 square feet (USACE 2010a). Excavation efforts encountered and disposed of approximately 201 pounds of PCB light ballasts, 350 pounds of lead batteries, 4,100 pounds of lead debris, and approximately 10 gallons of antifreeze. Contents recovered from drums at Site 7 (approximately 2,150 gallons) were containerized and shipped offsite for disposal. Approximately 100 tons of petroleum-stained soil encountered during excavation efforts was excavated and containerized for offsite disposal.

At the conclusion of the 2009 field season, approximately 136 tons of nonhazardous waste, 2.7 tons of hazardous waste, and 182 filled drums were removed from the landfill (USACE 2010a). Fifty of the filled drums were transported offsite after being emptied and cleaned and more than 1,000 empty drums were cleaned, crushed, and returned to the landfill.

Waste encountered at Site 7 was consolidated and cleaned at a Hazardous Waste Accumulation Point (HWAP) on the gravel pad at Site 6. Drums containing liquid product

were transported to the HWAP, cut open, and pumped of their contents. Drums then were washed with a high-pressure hot water rinse within an open-top container express unit. Waste streams processed at the HWAP included DRO-contaminated soil, oil waste, PCB light ballasts, batteries, lead debris, antifreeze, and wash-water (USACE 2010a).

A 2-foot minimum landfill cap was constructed using material from an on-island borrow source south of Site 31. The cap was graded to promote surface runoff and prevent erosion. The landfill cap boundaries are shown on Figure A-6. Locations where debris was not encountered are noted as potentially having less than a 2-foot cap in order to maintain grade (USACE 2010a). On 20 November 2009, site closure was requested (Bristol Environmental Remediation Services [Bristol] 2009). On 7 December 2009, site closure was considered premature and denied by ADEC (USACE 2010a). In 2011, Site 7 was re-seeded and fertilized to assist vegetation growing on the surface of the landfill cap. A stabilization analysis was conducted by Bristol and determined the landfill cap met non-vegetative permanent stabilization requirements established in the 2011 Alaska Construction General Permit (USACE 2012).

In 2013, surface water was collected from three locations adjacent to the landfill cap and submitted to an offsite analytical laboratory for analysis of gasoline-range organics (GRO), DRO, RRO, benzene, toluene, ethylbenzene, and xylenes (BTEX), polycyclic aromatic hydrocarbons (PAH), PCBs, and both dissolved phase and total Resource Conservation and Recovery Act (RCRA) metals with nickel and zinc. The collection of shallow groundwater samples was attempted using a screened drive point and hand tools. Refusal was met between 1 and 3 feet bgs at four different locations northeast of the landfill cap. Surface water and attempted groundwater locations are shown on Figure A-6. Surface water sample results were compared to the applicable surface water criteria (18 AAC 70) listed in the DD for TAH, TAqH, and no sheen (USACE 2009a). No exceedances of the criteria were found (USACE 2014b). Furthermore, the surface water results for metals, PCBs, VOCs, and PAHs did not exceed any screening criteria for drinking water.

At the time of this review, LUCs to limit groundwater use and prevent construction of buildings on top of the landfill had not been implemented.

4.2.2 Operations and Maintenance

Visual monitoring of the landfill cap by the USACE quality assurance representative occurred in September 2011, July 2012, and August 2013; observations are noted in the 2011, 2012, and 2013 Site Inspection Checklists (Craner 2011; Shewman 2012; Geist 2013). During site inspections, ponded water was observed against the north, west, and south sides of the landfill cap. Vegetative cover was estimated at 70 percent on the cap surface and 60 percent on the side slopes. The cap was noted as appearing structurally sound and stable with no visible erosion, leakage, or debris. Grass seed was spread by Bristol on 13 September 2011 to encourage vegetative re-growth in areas noted as bare (Craner 2011). A visual inspection of the landfill cap also was conducted as part of this review in September 2013 and is described in Section 6.9.

5.0 PROGRESS SINCE THE LAST REVIEW

This is the first Periodic Review for Site 7.

(intentionally blank)

6.0 PERIODIC REVIEW PROCESS

As previously stated, this site is not regulated under CERCLA; however, to maintain administrative consistency, this Periodic Review was conducted using the following guidelines:

- EPA Comprehensive Five-Year Review Guidance (EPA 2001)
- Clarifying the Use of Protectiveness Determinations for CERCLA Five-Year Reviews. (EPA 2012b)
- EPA Five-Year Review Summary Form Template (EPA 2001)

6.1 ADMINISTRATIVE COMPONENTS OF THE PERIODIC REVIEW PROCESS

USACE notified potentially interested parties of the occurrence of the review using newspaper notices, emails, and distribution of a fact sheet (described in Section 6.2) in the fall of 2013. The Periodic Review team consisted of individuals from USACE with technical support provided by Jacobs. The Periodic Review included the following components: document reviews; site inspection; interviews with the state regulatory agency and community members; an assessment of protectiveness of the remedies; community notification and involvement; and development of this Periodic Review Report. Documentation of the site inspection is located in Appendices C and D. Interview documentation is included in Appendix E.

6.2 COMMUNITY NOTIFICATION AND INVOLVEMENT

Public participation has been an important component of the remediation process at the Northeast Cape FUDS. A Restoration Advisory Board (RAB), comprised of community members and other interested parties, was established January 2000. Biannual RAB meetings are held to keep the public informed of ongoing project activities at the Northeast Cape FUDS. In the past, RAB meetings have been held more frequently, as needed. Detailed minutes are recorded and distributed following each meeting. Under the Technical Assistance for Public Participation program, the RAB is served by a technical advisor to provide

technical guidance and comments on work plans, reports, proposed remedies, and potential environmental and human health impacts.

The community was notified of, and given opportunity to provide input to, the Periodic Review. The general public was notified of the Periodic Review with public notices placed in the *Nome Nugget*, 18 and 19 August 2013. In addition, a flyer containing the same information was mailed to select community members and ADEC in September 2013. The public notices and flyer included information regarding the simultaneous Five-Year Reviews and Periodic Reviews occurring at 17 other Northeast Cape sites.

Community interviews for this Periodic Review were conducted (in conjunction with community interviews for the simultaneous Periodic Reviews and Five-Year Reviews) by Jacobs personnel at the first 2014 RAB meeting, 15 and 16 January. Additional phone interviews were conducted by Jacobs personnel, 4 and 6 February 2014. The interview concerns related specifically to Site 7 or describing sitewide concerns are summarized in Section 6.10. The complete interview record, public notices, and flyer are provided in Appendices E and F.

Following USACE signature of the final review and distribution of the final report, a second fact sheet describing the findings of the review will be distributed in combination with the results of the Periodic Review. A copy of this Periodic Review Report will be added to three information repositories (Sivuqaq Corporation Building (Lodge) in Gambell, Alaska; Savoonga City Hall, Savoonga, Alaska; Alaska Resource Library and Information Services, Anchorage, Alaska).

6.3 DOCUMENT REVIEW

The DD for Site 7 was reviewed for the site history and to identify RAOs, contaminants of potential concern (COPC), COCs, and cleanup levels. The potential for changes to standards identified as applicable requirements in the DD and/or newly promulgated standards that may affect the protectiveness of the remedies are evaluated in Appendix B and discussed in

Section 7.0. The following documents were reviewed for updates to applicable requirements and new toxicity information:

- ADEC 18 AAC 75, Oil and Other Hazardous Substances Pollution Control (ADEC 2012)
- ADEC Cleanup Levels Guidance (ADEC 2008)
- EPA Integrated Risk Information System retrieved from http://www.epa.gov/iris/_(EPA 2013)

In addition to the documents mentioned above, the following documents also were reviewed to assess the protectiveness of the remedy:

- RI/feasibility study reports (when necessary to clarify information in the DD)
- The Human Health and Ecological Risk Assessment (USACE 2004b)
- Removal action report
- Monitoring reports

Key documents referenced during this Periodic Review are listed in Section 12.0 of this Report.

6.4 DATA REVIEW

The remedy at Site 7 is to expose underlying drums/debris by disturbing the upper approximately 1 foot of fill across the areas with mapped metallic anomalies to determine if near-surface drums are present, remove identified drums and incidental contaminated soils, cap the landfill, conduct periodic visual monitoring of the cap for settlement and erosion for five years, and implement LUCs. The remedy was initiated in 2009. During drum removal efforts, several waste streams were encountered. Waste characterization samples were collected from excavated soil and drums containing drilling cuttings and recovered product. Waste characterization sample results were reviewed to identify any previously unidentified contaminants and/or changes in maximum detected concentrations of known COCs.

6.5 RECOVERED PRODUCT WASTE CHARACTERIZATION

A total of 24 liquid-containing accumulation drums resulted from the removal activities at Site 7. Each drum was field screened using CLOR-D-TECT test kits and results greater than 1,000 parts per million required fixed laboratory analysis. Three drums failed the field screening test and one primary and one duplicate sample were composited for analysis. Sample results identified lead at 200 mg/kg. The three drums were classified as hazardous waste due to lead results and the presence of chlorinated paraffins in excess of 1,000 mg/kg. A fourth drum was verified to contain nearly 100 percent ethylene glycol antifreeze.

In addition to liquid wastes, oil sludge and kitty litter contaminated with oil were managed at the HWAP. Three primary samples and one duplicate sample were collected from a combination of two oil sludge drums and 17 drums of kitty litter contaminated with oil. These samples indicated the presence of Aroclor 1248 up to 2.4 mg/kg and Aroclor 1254 at 1.1 mg/kg.

6.6 EXCAVATED SOIL

COPCs in soil at Site 7 identified in the DD include DRO, arsenic, chromium, lead, and PCBs. At the time of the DD (USACE 2009a) these contaminants were believed to be limited and were planned to be capped or removed as grossly contaminated soils. Grossly contaminated soils encountered during drum removal efforts were excavated in 2009. Confirmation samples were not collected following removal of grossly stained soils (USACE 2010a). Table 6-1 presents maximum known concentrations at the time of the DD and the maximum concentrations detected in excavated soil waste accumulated at the HWAP.

Table 6-1
Site 7 Maximum Detected Concentrations in Excavated Soil

Analyte	Cleanup Level ^a	Unit DD Maximum Concentration		Maximum Concentration in Excavated Soil	
DRO	9,200	mg/kg	32,000	11,000	
Arsenic	11	mg/kg	17.3	0.0052 J	
Chromium	50	mg/kg	75	0.0053 J	
Lead	400	mg/kg	460	1.4	
PCBs	1	mg/kg	> 0.5	1 J	

Notes:

Cleanup level reported in the DD (USACE 2009a)

BOLD = result exceeds cleanup level

J = The analyte was positively identified; the quantitation is an estimation

6.7 SURFACE WATER

The COC in surface water is DRO. In 1994, DRO was detected in a collocated surface water and sediment sample at concentrations of 8.9 mg/L (average of triplicate samples) and 4,900 mg/kg, respectively (USACE 2007c). Groundwater grab samples collected in 2001, approximately 200 feet downgradient of the surface water exceedance, did not contain DRO greater than cleanup levels.

In 2013, additional surface water sampling was conducted to evaluate existing surface water conditions at Site 7 (USACE 2014b). The 1994 surface water sampling location was not available for resampling in 2013 because the area previously had been covered by the landfill cap in 2009. As an alternative, site surface water was collected from three ponds located near the base of the landfill cap. The locations were selected as a representative subset of site surface water. Surface water sampling locations are shown in Figure A-2. Surface water samples were analyzed for DRO, RRO, GRO, BTEX, PAHs, PCBs, RCRA metals, nickel, and zinc. Analytical results did not exceed the surface water criteria for TAH/TAqH and no sheen specified in the DD. Furthermore, the surface water results for metals, PCBs, VOCs, and PAHs did not exceed any screening criteria for drinking water (USACE 2014b).

6.8 GROUNDWATER

RRO, chromium, lead, and nickel previously have been detected in shallow groundwater above ADEC drinking water standards at Site 7 (USACE 2009a). The DD did not include a remedy for groundwater contamination at Site 7 because shallow groundwater at Site 7 was not a current or reasonably expected potential future source for drinking water. At the time of this Periodic Review, LUCs to limit groundwater use and prevent construction of buildings on top of the landfill had not been implemented. In 2013, groundwater sampling was attempted northeast of the landfill cap (USACE 2014b). Drive point refusal was encountered at depths ranging from 6 to 30 inches bgs, due to large rocks. Groundwater was not encountered during the attempts, and it is not clear whether groundwater is present onsite.

Historically, sampling groundwater at this site has been difficult. Previous efforts to install temporary well points were successful at location WP 7-1 in 2001, yet required approximately three days before sampling could take place due to a low groundwater production rate. In some cases, the sampling points purged dry after 48 hours, without producing the required sampling volume (USACE 2007c). Two groundwater grab samples (WP7-2 and WP7-3) collected in 2001 were obtained by digging "pits" 36 to 40 inches bgs and allowing them to fill with water prior to sampling.

Significant effort will be required to install and maintain permanent monitoring wells at Site 7. The use of a tracked drill rig, in addition to air rotary or sonic drilling methods, likely would be needed for the successful installation of a monitoring well at this location. Walking the needed drill rig to boring locations would subject the fragile tundra and surface vegetation to disturbance. Additionally, any monitoring wells likely would be subject to frost jacking due the extreme variability of seasonal conditions.

6.9 RECOMMENDATIONS FOR SITE 7

The site inspection for this Periodic Review was conducted on 13 September 2013. The site inspection team consisted of USACE consultants from Jacobs. The team did not identify any

2/6/2015

active monitoring wells, signs of site disturbance (such as excavations), or changes in land use from those described in the DD. The site inspection checklist is located in Appendix C.

The site inspection team made the following recommendations:

- Implement LUCs to limit groundwater use and prevent construction of buildings on top of the landfill as described in the DD (USACE 2009a) within five years of this review. The timeframe for implementing this milestone will coincide with the remedy implementation of LUCs at other Northeast Cape sites.
- Conduct an additional Periodic Review to evaluate remedy implementation no later than five years from the date of this review. The second Periodic Review could occur sooner if removal of the debris protruding through the surface of the southeastern edge of the landfill and the implementation of LUCs occurs. The second Periodic Review will make recommendations regarding future periodic reviews as Site 7.

The landfill cap at Site 7 was observed in good condition with no apparent signs of erosion or cracking. The soil used for vegetative cover was observed to be very coarse, making vegetative growth difficult and sparse. There was a small amount of debris protruding from the cap on the southern side of the cap near the armored rock (Photo No. 15, Appendix D). Several metal items were observed in ponds located immediately north of the landfill cap (Photo Nos. 6, 7, 9, 10, 11, 18, and 19, Appendix D). A few rusted open drums were observed in ponds located to the north and southeast of the landfill cap (Photo Nos. 6 and 19, Appendix D). Bentonite was observed on the ground surface and thought to be an abandoned monitoring well southeast of the landfill cap (Photo No. 17, Appendix D).

6.10 INTERVIEWS

During the course of this Periodic Review, interviews were conducted with representatives from several agencies and community members associated with the Northeast Cape FUDS to incorporate all sites within Northeast Cape requiring a Five-Year Review or Periodic Review. Concerns related specifically to Site 7 are summarized below. The complete Interview Record Forms are provided in Appendix E.

Five members of the Kukulget Inc. Board of Directors provided responses to interview questions in a group format. Their general impressions of the cleanup efforts at the Northeast Cape FUDS were good, but they had several remaining questions, concerns, and suggestions. Issues discussed during this group interview are summarized by topic below.

- Landfills were capped and reseeded with what was referred to as "local grass." The community members expressed concern with the lack of vegetative re-growth on the landfill cap and stated, "Grass can't grow on rocks."
- One member, who previously had worked with Bristol during the remedial actions at Site 7 in 2009, said engines, an airplane, transformers, batteries, a road grader, and barrels were all seen beneath the area that was excavated. He indicated excavation efforts were limited to the surface, and these items remain onsite beneath the cap. He stated he did not understand the rationale behind removing large amounts of contaminated soil throughout Northeast Cape while significant quantities of potentially hazardous debris in the landfills remained and recommended opening up the cap to remove all remaining debris, as well as changing the cap material to soil, where vegetation can grow.
- Several members suggested adding signage to the perimeter of the landfills to notify site visitors of the presence of the landfill. They also suggested adding monitoring wells to landfills and the MOC for continued groundwater monitoring and requested the monitoring wells be well marked to avoid being hit during the winter months when visibility of the stickup mounts may be obscured by snow.

Alaska Community Action on Toxics (ACAT) and Native Village of Savoonga Tribal Member Executive Director (Pamela Miller) and Environmental Health and Justice Program Director (Vi Waghiyi) provided responses to interview questions via email. Ms. Miller and Ms. Waghiyi indicated the tribe should be an official signatory to the DDs. Their general impression was that cleanup efforts at Northeast Cape were far from complete and, additionally, not protective of the health of the people living on the island. They had several additional questions, concerns, and suggestions, which are summarized by topic below.

- Ms. Miller and Ms. Waghiyi stated they believed contamination to persist beneath the landfill caps installed at Sites 7 and 9. They indicated this is of great concern for human health and expressed worry regarding leachate from the landfills affecting the Sugitughned River watershed, fish and wildlife, and human health.
- Long-term monitoring of groundwater is requested to occur at sites where monitoring wells have been removed, as well as installation of new monitoring wells at key locations, such as downgradient of the MOC and landfill sites.

Various other community members also voiced concerns. Issues discussed during these individual interviews related specifically to Site 7 are summarized below.

Mitchell Kiyuklook, President of the Native Village of Savoonga: Mr. Kiyuklook indicated the Northeast Cape FUDS has had significant impacts on the surrounding community, including increased incidences of cancer, high blood levels of PCBs, and decreases in the number of seals on the island and fish in the Sugitughneq River. Mr. Kiyuklook had concerns regarding remedies identified in the DDs, including the sitespecific cleanup levels established for petroleum hydrocarbons and capping the Site 7 landfill while it still contains a large number of remaining buried drums. Mr. Kiyuklook indicated materials were collected from the Northeast Cape FUDS for construction around the island. Thus, contaminants may be present throughout St. Lawrence Island. Mr. Kiyuklook did not feel as though he was well informed about the activities and progress at Northeast Cape. He indicated that, although the information may have been presented at meetings, the community required a better explanation of what the regulations mean and how the cleanup levels were established. He suggested information be provided to the community before the reports are finalized, which can sometimes be up to a year after work has been completed. Mr. Kiyuklook requested reindeer on the island be re-sampled for levels of PCBs now that PCB cleanup efforts have been completed. Lastly, Mr. Kiyuklook mentioned a recent conference call with Native American Lands Environmental Mitigation Program, ACAT, and Ron Scurdato, during which was discussed trace levels of radiation that were identified on metals shipped from Northeast Cape for recycling. He indicated he would like this new information investigated further.

7.0 TECHNICAL ASSESSMENT

The protectiveness of the selected remedy is analyzed in this technical assessment, which was

completed by answering three questions, as described below.

7.1 QUESTION A

Question A: Is the remedy functioning as intended by the DD?

Answer: Yes.

This question was answered by considering the remedy's implementation status outlined in

Section 4.0 and available information reviewed in Section 6.0 and comparing the remedy to

the requirements in the DD. Remedial action performance, monitoring, LUCs, and indicators

of potential problems were assessed as applicable.

Remedial Action Performance

The selected remedy for Site 7 has several components, including drum removal and

installation of a 24-inch minimum soil cap. The site inspection, conducted on 13 September

2013, verified the construction of a landfill cap and noted the integrity of the cap was in good

condition without evidence of erosion or cracking. A small amount of debris was identified

protruding through the surface of the southeastern edge of the landfill. The site inspection also

identified metal debris in several surface water bodies adjacent to the landfill cap that may

pose safety risks to future site visitors.

System Operations and Maintenance

An additional visual inspection event is recommended for the Site 7 landfill cap. The

inspection is recommended to occur following the removal of the identified debris protruding

through the surface of the southeastern edge of the landfill and implementation of LUCs. The

second event is recommended to occur within five years of this review. Additional monitoring

events should be documented within the second Periodic Review, at which time, the need for

future reviews will be evaluated.

7-1

HTRW-J07-05F45902-J09-0004

Implementation of Institutional Controls and Other Measures

The selected remedy for Site 7 included the implementation of LUCs to limit groundwater use

and prevent construction of buildings of top of the landfill. At the time of this review, LUCs

had not been implemented.

Opportunities for Optimization

Identified debris on the surface of the southeastern edge of the landfill cap should be

removed. Metal debris identified in adjacent water bodies should be removed.

Early Indicators of Potential Issues

None.

7.2 QUESTION B

Question B: Are the exposure assumptions, toxicity data, cleanup levels, and RAOs used at

the time of the remedy selection still valid?

Answer: Yes.

Question B was answered by evaluating the effects of cleanup level or action limit changes in

applicable requirements and exposure assumptions that were used at the time of remedy

selection that may affect its protectiveness. In addition, COCs listed in the applicable DD

were evaluated to determine whether new standards or new data obtained after the DDs were

signed to become COPCs (Appendix B).

This evaluation was completed according to EPA's guidance for applicable or relevant and

appropriate requirements (ARAR) (EPA 2001):

"Generally you should only consider changes in standards that were identified as ARARs in the Record of Decision (ROD), then identify any newly

promulgated standards for COPCs, and TBCs [To Be Considered] identified in

the ROD that bear on the protectiveness of the remedy. As such, you should review any newly promulgated standards, including revised chemical-specific requirements (such as MCLs [maximum contaminant levels], ambient water

quality criteria), revised action and location-specific requirements, and state

standards if there were considered ARARs in the ROD. In evaluating a change

7-2

in a standard that was identified as an ARAR in the ROD, or a newly promulgated standard or TBC, you should establish whether the new

requirement indicates that the remedy is no longer protective."

The evaluation of new or changed standards was accomplished by first identifying the

applicable standard and then comparing it to the current standard. Potential cleanup levels for

COPCs not identified in the DD were compared to current applicable state cleanup standards.

Table B-1 in Appendix B summarizes the evaluation of COCs and COPCs.

Changes in Standards and To Be Considered

The DD listed 18 AAC 75.341 as the applicable requirement for soil and 18 AAC 75.345 and

18 AAC 70.020(b) for groundwater. For those compounds listed as COCs, the cleanup level

either has not changed or the site-specific values were calculated using a Method Four risk

assessment.

Changes in Exposure Pathways

None identified.

Changes in Toxicity and Other Contaminant Characteristics

None identified.

Changes in Risk Assessment Methods

None identified.

Expected Progress Toward Meeting Removal Action Objectives

RAOs are expected to be met following removal of debris identified during the 2013

Site Inspection and the implementation of LUCs to limit groundwater use and prevent

construction of buildings on top of the landfill.

7-3

HTRW-J07-05F45902-J09-0004

7.3 QUESTION C

Question C: Has any other information come to light that could call into question the

protectiveness of the remedy?

TECHNICAL ASSESSMENT SUMMARY

Answer: No.

7.4

This question was answered by considering whether ecological risks have been addressed adequately at the site, if the site is subject to natural disasters, and any plans for potential land use or land use changes.

Attainment of RAOs is measured through collection of empirical data, and data were compared against applicable requirements. The remedy selected for Site 7 is functioning as intended by the DD, but implementation is not yet complete. It is expected to be protective upon completion.

7-4

8.0 ISSUES

This section summarizes issues and concerns related to current site operations, conditions, or activities that were identified during this Periodic Review. Issues were evaluated to determine whether they affected the current or future protectiveness of the associated remedy. Table 8-1 summarizes issues identified that affect the protectiveness of the remedy (Issue 1) and issues identified as not affecting the protectiveness of the remedy (Issues 2 and 3). Unresolved concerns raised by the community also are summarized and discussed.

Table 8-1 Issues Identified

Issue No:	Issue	Reference	Affects Current Protectiveness? (Yes/No)	Affects Future Protectiveness? (Yes/No)
1	LUCs to limit drinking water use and prevent construction of buildings on top of the landfill have not been implemented.	USACE 2009a USACE 2009b	No	Yes
2	The 2013 site inspection identified debris protruding from the landfill cap.	2013 Site Inspection (Appendix C)	No	No
3		2013 Site Inspection (Appendix C)	No	No

8.1 COMMUNITY ISSUES

Issues raised by the community regarding cleanup activities at Northeast Cape FUDS were identified through community interviews, RAB meeting minutes, public meeting minutes, and letters to the EPA. Issues related specifically to Site 7 or describing sitewide concerns have been summarized below with their current status.

The communities of St. Lawrence Island would like the tribes instituted as official signatories/Parties to any RODs (ACAT 2009; Community Interview 2013, Appendix E)

The Corps cannot seek Tribal signatures on RODs because the tribe does not have jurisdiction over the land itself. CERCLA regulations require that Indian tribes have jurisdiction over the site in order to be afforded substantially the same treatment as states (USACE 2010b).

Lichen is prominent throughout the site and has not been sampled for contaminants. Reindeer populations frequent this area and are used for subsistence (RAB 2012a).

Lichen has not been evaluated for contaminants at Northeast Cape. The U.S. Department of Health and Human Services (DHHS) performed a health consultation in 2001 and determined reindeer exposures to site-related contaminants are low. Detectable health effects are not expected in individuals consuming reindeer muscle and fat on St. Lawrence Island (DHHS 2001). The risk assessment conducted for Northeast Cape evaluated reindeer as an ecological endpoint and determined the cross fox represented a more highly exposed terrestrial mammal because it has a smaller home range than reindeer and, as a carnivore, is at a higher trophic level. The results of the evaluation indicated the ecological hazard estimate for the cross fox was below the departure criterion of 1.0 for all sites (USACE 2004b).

A community member indicated there was a pipeline break between the Native Village of Northeast Cape and the Site 7 Landfill. He would like this area located and tested (RAB 2012a)

The area (identified as an additional pipeline break site during the 2012 December RAB meeting) was included as an area of investigation during the 2013 field season. Analytes were not identified at concentrations greater than site-specific cleanup levels (USACE 2014a).

ACAT would like cleanup levels to be reevaluated given the multiple health burdens that affect the community (EPA 2012c).

Cleanup levels used for the Northeast Cape were developed based on the Human Health and Ecological Risk Assessment, Washington Administrative Code, and AAC. They are considered protective of future residential use (USACE 2009a, 2009b, 2004b).

Sampling was not conducted within the landfill at Site 7 following remedial activities in 2009. It is not clear whether contaminants remain above cleanup levels below the landfill cap at Site 7 (USACE 2010a; EPA 2012a).

Visual monitoring of Site 7 is recommended to ensure the remedy remains protective of human health and the environment. As previously established, shallow groundwater near the landfill cap is slow to recharge and does not produce water in sufficient quantities to provide drinking water. As a result, groundwater monitoring is considered unnecessary; however, monitoring of nearby surface water is recommended (EPA 2012a).

Responses to questionnaires identified a few areas where additional contamination related to FUDS activities may be present. Community members identified potentially hazardous debris beneath the landfill cap at Site 7 (Section 6.9 and Appendix E).

As part of the selected remedy, an intrusive investigation was conducted in 2009 to identify and remove any large caches of drums with potentially hazardous contents from the Site 7 landfill. This investigation is detailed in Section 3.2.1.

9.0 RECOMMENDATIONS AND FOLLOW-UP ACTIONS

Recommendations and follow-up actions have been identified to address the issues presented in Section 8.0. Table 9-1 presents these recommendations and identifies Issue 1 as affecting protectiveness and Issues 2 and 3 as not affecting protectiveness.

Table 9-1
Recommendations and Follow-up Actions

Issue	Recommendations/ Follow-up Actions	Party Responsible	Regulatory	Milestone	Affects Protectiveness? (Yes/No)	
No.			Party	Date	Current	Future
1	Implement LUCs following completion of the remedial action fieldwork, as described in the DD.	USACE	ADEC	2018	No	Yes
2	Remove debris protruding from the landfill cap.	USACE	ADEC	2018	No	No
3	Remove debris identified in and around ponds adjacent to the landfill cap.	USACE	ADEC	2018	No	No
1,2,3	Conduct an additional Periodic Review of Site 7	USACE	ADEC	2019	No	No

10.0 PROTECTIVENESS STATEMENT(S)

The remedy at Site 7 is expected to be protective of human health and the environment upon its completion. In the interim, no exposure pathways that could result in unacceptable risks have been noted.

11.0 NEXT REVIEW

Future periodic reviews for Site 7 are necessary to evaluate remedy completion. The next Periodic Review is due on or before 19 June 2019.

12.0 REFERENCES

- ACAT (Alaska Community Action on Toxics). 2009. (11 November). Thank you letter from Pamela Miller (ACAT) and Vi Waghiyi (ACAT) to Mathy Stanilaus (EPA). Includes *Tribal Representatives from St. Lawrence Island, Alaska, and the Alaska Community Action on Toxics (ACAT) Concerns About Ongoing U.S. Army Corps of Engineers Cleanup Work at the Northeast Cape and Gambell.* Letter from Dennis McLerran, Regional Administrator (EPA) to Colonel Richard Koenig, District Commander (USACE). FRMDs F10AK069603_08.01_0082_a and F10AK096903_08.01_0519_a.
- ADEC (Alaska Department of Environmental Conservation). 2012 (8 April). *Oil and Other Hazardous Substances Pollution Control* (18 AAC 75).
- ADEC. 2011 (1 October). Oil and Other Hazardous Substances Pollution Control. "Groundwater use." (18 AAC 75.350).
- ADEC. 2008 (9 June). *Cleanup Levels Guidance*. Division of Spill Prevention and Response. Contaminated Sites Program.
- ADEC. 2007a (17 October). *ADEC Comments on the Northeast Cape Proposed Plan*. Letter from Jeff Brownlee (ADEC) to Carey Cossaboom (USACE). FRMD No. F10AK096903 05.08 0502 a.
- ADEC. 2007b (24 May). *ADEC Comments on the Northeast Cape 350 Determination*. Letter from Jeff Brownlee (ADEC) to Carey Cossaboom of USACE. May 24, 2007. FRMD No. F10AK096903 05.07 0501 a.
- Bristol Environmental Remediation Services, LLC. 2009 (20 November). Request for Site 7 Landfill Closure at Northeast Cape, St. Lawrence Island, Alaska. Technical Memorandum. St. Lawrence Island, Alaska. FRMD No. F10AK096905_07.08_0501_a.
- Craner, Jeremy. 2011 (17 September). Visual Inspection Checklist (Post-Closure) Site 7 Landfill and Site 9 Landfill. FRMD Nos. F10AK096903_07.11_0500_p and F10AK096905_07.11_0500_p.
- DHHS (U.S. Department of Health and Human Services). 2001 (21 September). *Health Consultation: Exposure Investigation, Investigation of Persistent Organic Pollutants in Reindeer on St. Lawrence Island*. N.E. Cape White Alice Site (a/k/a N.E. Cape Site). St. Lawrence Island, Alaska, FRMD No. F10AK096903_03.11_0007_a.
- EPA (U.S. Environmental Protection Agency). 2013. *Integrated Risk Information System (IRIS)*. Retrieved from http://www.epa.gov/IRIS/.

- EPA. 2012a (November). Environmental Protection Agency (EPA) Region 10's Evaluation of Army Corps of Engineers Cleanup of FUDS at N.E. Cape and Gambell, St. Lawrence Island, Alaska. FRMD Nos. F10AK0969603_01.07_0011_a and F10AK069603_01.07_0500_a.
- EPA. 2012b (13 September). Memorandum Clarifying the Use of Protectiveness Determination for Comprehensive Environmental Response, Compensation, and Liability Act Five-Year Reviews. OSWER No. 9200.2-111.
- EPA. 2012c (15 February). December 2011 Public Meetings on Saint Lawrence Island Regarding Environmental Health and Cleanup Issues, Proposed Action Items Resulting from the Meeting. Letter from Sylvia Kawabata, Assessment and Brownfields Unit Manager (EPA) to December Dialogue Meeting Participants. FRMD No. F10AK096904 08.10 0013 a.
- EPA. 2010a (23 March). Letter from Dennis McLerran, Regional Administrator (EPA) to Pamela Miller, Executive Director and Vi Waghiyi, Program Director of the Alaska Community Action on Toxics (ACAT). FRMDs F10AK096903_01.01_0503_a and F10AK069603_01.01_0009_a.
- EPA. 2010b (23 March). *Tribal Representatives from St. Lawrence Island, Alaska, and the Alaska Community Action on Toxics (ACAT) Concerns About Ongoing U.S. Army Corps of Engineers Cleanup Work at the Northeast Cape and Gambell.* Letter from Dennis McLerran, Regional Administrator (EPA) to Colonel Richard Koenig, District Commander (USACE). Includes Thank you letter from Pamela Miller (ACAT) and Vi Waghiyi (ACAT) to Mathy Stanilaus (EPA). FRMDs F10AK069603_08.01_0082_a and F10AK096903_08.01_0519_a.
- EPA. 2001 (June). *Comprehensive Five-Year Review Guidance*. EPA. 540-R-01-0007. OSWER No. 9355.7-03B-P. Office of Emergency and Remedial Response. Washington, D.C.
- Geist, Lisa. 2013 (7 August). Visual Inspection Checklist (Post-Closure) Site 7 Landfill and Visual Inspection Checklist (Post-Closure) Site 9 Landfill. FRMD Nos. F10AK096903 07.11 0503 p and F10AK096905 07.11 0502 p.
- Kukulget, Inc. 2012 (23 April). *Right of Entry*. Letter from Morris Toolie, Jr., President (Kukulget, Inc.) to Thomas Kretzschmar, Real Estate Division Chief (USACE).
- Patton, W. and B. Csejtey. 1980. Geologic map of St. Lawrence Island, Alaska: U.S. Geological Survey Miscellaneous Investigation Series. Map I-1203. 1 sheet, scale 1:250,000.
- RAB (Restoration Advisory Board). 2012a (27 June). *St. Lawrence Island Restoration Advisory Board and Public Meeting, Meeting Minutes*. Teleconference. FRMD No. F10AK096904_08.10_0010_a.


- RAB. 2012b (5 December). St. Lawrence Island Restoration Advisory Board and Public Meeting, Meeting Minutes. City Hall, Savoonga, Alaska. FRMD No. F10AK096904 08.10 0019 p.
- Shewman, Aaron. 2012 (26 July). Visual Inspection Checklist (Post-Closure) Site 7 Landfill and Site 9 Landfill. FRMD Nos. F10AK096903_07.11_0501_p and F10AK096905_07.11_0501_p.
- U.S. Army. 2013 (24 April) *Department of the Army Right-of-Entry for Environmental Assessment and Response*. Saint Lawrence Island, Alaska. No. DACA85-8-12-00046. Agreement between the U.S. Government, Kukulget, Inc. and Sivuqaq, Inc. beginning on 1 June 2013.
- USACE (U.S. Army Corps of Engineers). 2014a. 2014 Five-Year Review. Pre-Draft. (Unpublished).
- USACE. 2014b (February). 2013 Sampling Conducted in Conjunction with the 2013 Five-Year Review at Northeast Cape. Final. St. Lawrence Island, Alaska. Prepared by Jacobs Engineering Group Inc. FRMD No. F10AK096903_07.11_0504_p and F10AK096905_07.11_0503_p.
- USACE. 2012 (June). *Northeast Cape HTRW Remedial Actions, Final Removal Action Report*, St. Lawrence Island Alaska. Prepared by Bristol Environmental Remediation Services, LLC. FRMD No. F10AK096903_07.08_0503_a.
- USACE. 2010a (May). *In-Situ Chemical Oxidation (Phase I) and Intrusive Drum*Removal/Landfill Cap, Site 7 Landfill Cap Construction Completion Report, Northeast
 Cape, St. Lawrence Island, Alaska. Prepared by Bristol Environmental Remediation
 Services, LLC. FRMD No.F10AK096905 07.08 0500 p.
- USACE. 2010b (9 April). Response to Three Specific Points Regarding the USACE FUDS on St. Lawrence Island, Alaska. Letter from Colonel Richard Koenig, District Commander (USACE) to Dan Opalski, Director of Environmental Cleanup (EPA). FRMD Nos. F10AK096903 01.01 0503 a and F10AK069603 01.01 0009 a.
- USACE. 2009a (June). Decision Document: Site 7 Cargo Beach Road Landfill, Containerized Hazardous, Toxic, and Radioactive Waste (CON-HTRW) Project #F10AK096905.

 Northeast Cape Formerly Used Defense Site (FUDS) St. Lawrence Island, Alaska. Signed 19 June 2009. FRMD F10AK096905_05.09_0500_a.
- USACE. 2009b (January). *Decision Document: Hazardous, Toxic, and Radioactive Waste* (HTRW) Project #F10AK096903. Northeast Cape Formerly Used Defense Site (FUDS) St. Lawrence Island, Alaska. Signed 3 September 2009. FRMD F10AK09603 05.09 0500 a.
- USACE. 2008 (May). *Proposed Plan for Site 7 Cargo Beach Road Landfill* FRMD No. F10AK096905_04.10_0500_a.


- USACE. 2007a (November). *Geophysical Survey, Northeast Cape, St. Lawrence Island*. Prepared by R&M Consultants, Inc. FRMD No. F10AK096905_03.10_0500_a.
- USACE. 2007b (4 April). Submission for Groundwater Use Determination (18 AAC 350) at Northeast Cape on St. Lawrence Island. Letter from Carey Cossaboom (USACE) to Jeff Brownlee (ADEC). FRMD No. F10AK096903 05.01 001 a.
- USACE. 2007c (March). *Feasibility Study*, Northeast Cape FUDS, St. Lawrence Island, Alaska. FRMD No. F10AK096904_04.09_0500_a and F10AK096905_0500_a.
- USACE. 2004a (10 May). Environmental Quality Formerly Used Defense Sites (FUDS)

 Program Policy. ER 200-3-1. http://munitionsresponsepartners.com/uploads/ER_200-3-1 Environmental Quality FUDS.pdf. Accessed 6 February 2015.
- USACE. 2004b (March). *Human Health and Ecological Risk Assessment*. Northeast Cape Installation. St. Lawrence Island, Alaska. Final. Prepared by MWH. FRMD No. F10AK096903_03.11_0005_a.
- USACE. 2001 (August). *GIS-based Historical Photographic Analysis*, St. Lawrence Island, Northeast Cape Sites, Alaska, Engineer Research & Development Center, Topographic Engineering Center.

APPENDIX A Figures



P:\StLawrenceIsland\\MXD\TO09_NorthEastCape\Site7PeriodicReview\Site7_NEC_StLawrence2014.mxd_wattta



APPENDIX B Cleanup Levels, Toxicity, and Risk Evaluation

U.S. Army Corps of Engineers Alaska District

SITE 7 CARGO BEACH ROAD LANDFILL FIRST PERIODIC REVIEW REPORT

NORTHEAST CAPE FUDS ST. LAWRENCE ISLAND, ALASKA

APPENDIX B CLEANUP LEVELS, TOXICITY, AND RISK EVALUATION

Formerly Used Defense Site F10AK0969-05

FINAL FEBRUARY 2015

TABLE OF CONTENTS

<u>SECTION</u>	PAGE
ACRONYMS AND ABBREVIATIONS	B-iii
INTRODUCTION	B-1
ADEC CLEANUP LEVELS USED FOR SOIL	B-1
CLEANUP LEVELS USED FOR SURFACE WATER	B-1
REFERENCES	R-3

ACRONYMS AND ABBREVIATIONS

AAC Alaska Administrative Code

ADEC Alaska Department of Environmental Conservation

COC contaminant of concern

COPC contaminant of potential concern

DD Decision Document

mg/kg milligrams per kilogram

mg/L milligrams per liter

NA not applicable

PCB polychlorinated biphenyl
TAH total aromatic hydrocarbon

TAqH total aqueous hydrocarbon

INTRODUCTION

Updates to regulations and chemical-specific toxicity data may occur over time. The effects of those changes are evaluated as part of the technical assessment conducted for the Site 7 Cargo Beach Road Landfill Periodic Review to ensure the selected remedy remains protective of human health. The evaluation of regulatory updates involves a two-step process followed by the evaluation of chemical-specific toxicity data updates (risk evaluation), if necessary. The evaluation process summarized below is explained in greater detail in the Periodic Review Report.

- The evaluation begins by determining whether any contaminants of potential concern (COPC) or contaminants of concern (COC) have new or changed standards since the time of the Decision Document (DD) (USACE 2009). All compounds identified in the DD are presented in Table B-1, below. Additionally, any compounds detected during remedy implementation that exceed the cleanup levels listed in the applicable or relevant and appropriate regulations have been included; therefore, Table B-1 includes more compounds than the DD list of COPCs and COCs.
- If a new or more stringent standard was identified, the COPC or COC was evaluated further. No new or more stringent standards were identified for Site 7 Cargo Beach Road; therefore, no COPCs or COCs were carried forward for the risk evaluation.

ADEC CLEANUP LEVELS USED FOR SOIL

For soil cleanup levels, the ADEC Method Two under 40-inch zone, migration to groundwater cleanup level (Title 18 of the Alaska Administrative Code [AAC], Chapter 75, Table B1), was applied for all compounds not listed in the DD as COCs. For those compounds listed as COCs, the cleanup level has either not changed or the site-specific values were calculated using a Method Four risk assessment.

CLEANUP LEVELS USED FOR SURFACE WATER

For surface water cleanup levels, the strictest cleanup levels or standards listed in 18 AAC 70 were used.

2/6/2015

Table B-1 **Evaluation of Changes in Chemical-Specific Standards**

COPCs/ COCs	DD- Established RAO for COCs	Source ^a	Current Alaska Cleanup Level	Is There A Newly Promulgated Cleanup Level Since Previous Review?	Is the New Level More Stringent than the Previous Standard?	
		Surface '	Water (mg/L)			
Diesel-range organics C ₁₀ to C ₂₅	No Sheen	18 AAC 70		No	NA	
Residual-range organics C ₂₅ to C ₃₆	No Sheen	18 AAC 70		No	NA	
Total aromatic hydrocarbons	0.01	18 AAC 70	0.01	No	NA	
Total aqueous hydrocarbons	0.015	18 AAC 70	0.015	No	NA	
Soil (mg/kg)						
Diesel-range organics C ₁₀ to C ₂₅	9,200	18 AAC 75 Method 4 /site-specific	250	No	NA	
Residual-range organics C ₂₅ to C ₃₆	9,200	18 AAC 75 Method 4 /site-specific	10,000	No	NA	
Arsenic	11 ^b	Site-specific Background	3.9	No	NA	
PCBs (sum)	1	18 AAC 75	1	No	NA	

Sources listed in the DD include the following:

¹⁸ AAC 75 Table C; 18 AAC 75 Table B1;

¹⁸ AAC 75 Method 4 risk-based residential cleanup level from the Feasibility Study (U.S. Army Corps of Engineers 2007)

^b DD-specified limit based on elevated background concentrations.

REFERENCES


- ADEC (Alaska Department of Environmental Conservation). 2008 (June). *Cleanup Levels Guidance*. Division of Spill Prevention and Response. Contaminated Sites Program.
- U.S. Army Corps of Engineers. 2009 (June). Decision Document: Site 7 Cargo Beach Road Landfill, Containerized Hazardous, Toxic, and Radioactive Waste (CON-HTRW) Project #F10AK096905, Northeast Cape Formerly Used Defense Site (FUDS).

 St. Lawrence Island, Alaska. Prepared by USACE-Alaska District, June 2009.
- U.S. Army Corps of Engineers. 2007 (March). *Feasibility Study*, Northeast Cape FUDS, St. Lawrence Island, Alaska. FRMD No. F10AK096904_04.09_0500_a and F10AK096905_0500_a.

2/6/2015

(intentionally blank)

APPENDIX C Site Inspection Checklists and Logbook



I. SITE INFORMATION		
Site name: Site 7- Cargo Beach Road Date of Inspection: 15 9/13/13		
Location and Region: NE (and and fill	EPA ID: AK9 799 F2999	
Agency, office, or company leading the	Weather/temperature:	
five-year review: USACE	Overcast ~40°F	
Remedy Includes: (Check all that apply) Landfill cover/containment Access controls Institutional controls Groundwater pump and treatment Other: Capping with Ide Attachments: Inspection team roste		
100 mm - 100	HECK ALL THAT APPLY)	
1. O&M site manager NONE	NONE	
Name	Title Date ce by phone (Phone no)	
2. O&M staff NONE	NONE	
Name	Title Date ce by phone (Phone no)	
3. Local regulatory authorities and response emergency response office, police department health, zoning office, recorder of deeds, or capply. Agency ADEC Contact Curtis Durking Name Interviewed at site at office at office problems, suggestions (Report attached)	Project Hanger 01/2014 Title Date Description of public health or environmental other city and county offices, etc.) Fill in all that Date Description of public health or environmental other city and county offices, etc.) Fill in all that	
Agency		
Name Interviewed ☐ at site ☐ at offi Problems, suggestions (☐ Report attached)	Title Date ce	
4. Other interviews (optional) (Report a	ttached)	

Site Name: Site 7

JACOBS Five-Year Review Site Inspection Checklist (2/12)

	III. ONSITE DOCUMENT	S & RECORDS VE	RIFIED
1.	O&M Documents O&M manual As-built drawings Maintenance logs Remarks: Record of Decision No. and site maps.	□Readily available □Readily available □Readily available □SID FOR SITE	☐Up to date MN/A☐Up to date MN/A
2.	Site-Specific Health and Safety Plan Contingency plan/emergency response plan Remarks:		☐Up to date ☐N/A ☐Up to date ☐N/A
3.	O&M and OSHA Training Records Remarks:	☐Readily available	□Up to date ►N/A
4.	Permits and Service Agreements Air discharge permit Effluent discharge Waste disposal, POTW Other permits: Remarks:	☐Readily available ☐Readily available ☐Readily available ☐Readily available	☐Up to date ☑N/A☐Up to date ☑N/A
5.	Gas Generation Records Remarks:	☐Readily available	□Up to date □XN/A
7.	Groundwater Monitoring Records Remarks:	☐Readily available	□Up to date ▼N/A
8.	Leachate Extraction Records Remarks:	[□Up to date □N/A
9.	Discharge Compliance Records Air Water (effluent) Remarks:	□Readily available □Readily available	
10	.Daily Access/Security Logs Remarks:		□Up to date \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\

Site Name: Site 7

JACOBS Five-Year Review Site Inspection Checklist (3/12)

10.4		IV.	 O&M COST 	S	GT-6/
1.0&M	Organization	100000000000000000000000000000000000000		Water and the same	
A STATE OF THE PARTY OF THE PAR	State in-house		☐ Contracto	or for State	
	PRP in-house	The state of the s			
	Federal Facility	y in-house	☐ Contracto	or for Federal Facility	
	Other USA				
					_
2. O&M	Cost Records	Alot A	VAILABLE	D 1001111115	
П	Readily availab	ole	□ Up to dat	e 6-54Reviews or all NE Cape Sites Breakdown attached	
l ī	Funding mecha	nism/agreeme	ent in place - f	or all NE Cape Sites	
Origin	al O&M cost es	stimate 58 5	1,587	Breakdown attached	
				v period if available	
			by year for review		1
From_	To_			Breakdown attached	
-	Date	Date	Total cost	5 11	
From_	To _		T . 1	Breakdown attached	
	Date	Date	Total cost	D 1.1	1
From_			T-4-1	Breakdown attached	
E	Date	Date	Total cost	Dunaled arrow attached	
From -	To _	Date	Total cost	Breakdown attached	
Erom			I otal cost	Breakdown attached	
FIOIII_	To _	Date	Total cost	Breakdown attached	
		ANTI-CENTERS.			
3. Unant	ticipated or Un	usually High	O&M Costs Duri	ng Review Period	
Descr	ibe costs and re	asons:	OF AVAILA	NONE	<u> </u>
				Company of the compan	_
		e anno e a como de des	All Marketin California Company	to to accept the same of	
32.44					
	V.	ACCESS A	ND INSTITUTIO	NAL CONTROLS	00.2
				N/A	
A. Fenci	ing				
75 G-37	cing damaged	□Loca	tion shown on site	map	
	3 0		s secured	•	
		N/A			
Ren	narks	-20020		105 J	
B. Other	r Access Restr	ictions	- June 1 Table 1	/ (ucs in
	ns and other se	AND COLUMN TO SERVICE AND ADDRESS OF THE PROPERTY OF THE PROPE	res	shown on site map	Deogres:
		ourly monda	⊠N/A	remedy includes	1 0
Ren	narks Sofe 5	2 cargo !	beach landt	ill has existing	
450		4 / 1		uildings are constr	ucted
The state of	10.			arounduater site 7	
In	1 1 11.1		,		
100	The second secon			te island. There is cul	er uy
8h	no road a	ciess to 8	nregreom en	ther on-island Villa	8.

JACOBS Five-Year Review Site Inspection Checklist (4/12)

	VI. GENERAL SITE CONDITIONS
A. L:	Roads damaged Location shown on site map Roads adequate N/A Remarks Cargo beach Road crosses over landfill cap.
	ther Site Conditions emarks
_	
	VII. LANDFILL COVERS ☑ Applicable □ N/A
	Andfill Surface Settlement (Low spots)
2.	Cracks
3.	Erosion
4.	Holes
5.	Vegetative Cover Grass Cover properly established No signs of stress Trees/Shrubs (indicate size and locations on a diagram) Remarks 501 is Very coarse waking Vegetative growth
6.	Alternative Cover (armored rock, concrete, etc.) N/A difficult Remarks Souther Corder of cap consist of armored rock
7.	Bulges
8.	Wet Areas/Water Damage
9.	Slope Instability Slides Location shown on site map No evidence of slope instability Areal extent Remarks

Site Name: Site 7

JACOBS Five-Year Review Site Inspection Checklist (5/12)

B. Benches Applicable N/A				
(Horizontally constructed mounds of earth placed across a steep landfill side slope to				
interrupt the slope in order to slow down the velocity of surface runoff and intercept and				
convey the runoff to a lined channel.)				
1. Flows Bypass Bench Location shown on site map N/A or okay				
Remarks				
2. Bench Breached				
3. Bench Overtopped				
C. Letdown Channels				
(Channel lined with erosion control mats, riprap, grout bags, or gabions that descend down				
the steep side slope of the cover and will allow the runoff water collected by the benches to				
move off of the landfill cover without creating erosion gullies.)				
1. Settlement				
Areal extent Depth				
Remarks				
2. Material Degradation				
Material type Areal extent				
Remarks				
3. Erosion				
4. Undercutting				
TOTAL CONTROL				
5. Obstructions Type No obstructions				
☐ Location shown on site map Areal extent				
Size				
Remarks				
6. Excessive Vegetative Growth Type				
☐ No evidence of excessive growth				
☐ Vegetation in channels does not obstruct flow				
☐ Location shown on site map Areal extent				
Remarks				

2110	24			
Site	Name:	Sile-	1	

JACOBS Five-Year Review Site Inspection Checklist (6/12)

D. Cover Penetrations Applicable N/A
1. Gas Vents ☐ Active ☐ Passive ☐ Properly secured/locked
☐ Functioning ☐ Routinely sampled ☐ Good condition
☐ Needs maintenance ☐ Evidence of leakage at penetration
□ N/A
Remarks
· · · · · · · · · · · · · · · · · · ·
2. Gas Monitoring Probes
☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled
☐ Good condition ☐ Evidence of leakage at penetration ☐ Needs maintenance ☐ NA
Remarks
Rollidiko
3. Monitoring Wells (within surface area of landfill)
☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled
☐ Good condition ☐ Evidence of leakage at penetration
☐ Needs Maintenance
Remarks
4. Leachate Extraction Wells
☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled
☐ Good condition ☐ Evidence of leakage at penetration
☐ Needs Maintenance ☐ N/A
Remarks
5 Settlement Memorate Directed
5. Settlement Monuments
Remarks
E. Gas Collection and Treatment Applicable \N/A
E. Gas Collection and Treatment
☐ Flaring ☐ Thermal destruction ☐ Collection for reuse
☐ Good condition ☐ Needs Maintenance ☐ N/A
Remarks
2. Gas Collection Wells, Manifolds and Piping
☐ Good condition ☐ Needs Maintenance ☑N/A
Remarks
3. Gas Monitoring Facilities (e.g., gas monitoring of adjacent homes or buildings)
☐ Good condition ☐ Needs Maintenance ☒N/A
Remarks

Site Name:	Site
------------	------

JACOBS Five-Year Review Site Inspection Checklist (7/12)

F. Cover Drainage Layer 1. Outlet Pipes Inspected Remarks	☐ Applicable ☐ Functioning	⊠N/A ⊠N/A
2. Outlet Rock Inspected Remarks		ØN/A
G. Detention/Sedimentation Ponds 1. Siltation Areal extent Siltation not evident Remarks	Depth	MA)
2. Erosion Areal extent Erosion not evident Remarks		
3. Outlet Works Remarks	Applicable	SKN/A
4. Dam Remarks		
H. Retaining Walls 1. Deformations	Vertical displace	Deformation not evident ment
2. Degradation		

Site	Namer	F St	
	01	101	

JACOBS Five-Year Review Site Inspection Checklist (8/12)

I. Perimeter Ditches/Off-Site Discharge
1. Siltation
Areal extent Depth
Remarks
2. Vegetative Growth ☐ Location shown on site map ☐ N/A
☐ Vegetation does not impede flow
Areal extent Type
Remarks
3. Erosion
Areal extent Depth
Remarks
4. Discharge Structure ☐ Functioning ☐ N/A
Remarks
VIII. VERTICAL BARRIER WALLS ☐ Applicable ZN/A
1. Settlement Location shown on site map Settlement not evident
Areal extent Depth
Remarks:
2. Performance Monitoring
Type of monitoring
Performance not monitored Frequency
☐ Evidence of breaching
Head differential
Remarks:

JACOBS Five-Year Review Site Inspection Checklist (9/12)

IX. GROU	INDWATER/SURFACE WATI	ER REMEDIES
1 C 1 1 E 1 E	Applicable N/A	TIA-E-11- MAYA
1. Pumps, Wellhead Plus	Wells, Pumps, and Pipelines	Applicable K N/A
	All required wells properly of	agentin a
☐ Needs Maintenance		berating
	doned well togation	
on Sciether	n since of Site of	A disti2
The state of the s	pelines, Valves, Valve Boxes, an	d Other Appurtenances
1000	☐ Needs Maintenance	
Remarks NOT AP	PLICABLE	
3. Spare Parts and Equip		
☐ Readily available		
	☐ Needs to be provided	
Remarks NOT APP	PLICABLE	total 1 in the second
B. Surface Water Collection	n Structures, Pumps, and Pipeli	nes Applicable N/A
1. Collection Structures,		
	☐ Needs Maintenance	
The same of the sa		
	The second secon	
	tion System Pipelines, Valves, V	alve Boxes, and Other
Appurtenances	F137 1 36 2	
	☐ Needs Maintenance	
Remarks		
3. Spare Parts and Equip		21127 P. 211
☐ Readily available		
	☐ Needs to be provided	
Remarks		
32/2007		HSH HS THE STATE OF THE STATE O

Site Name: Site

JACOBS Five-Year Review Site Inspection Checklist (10/12)

C. T	reatment System Applicable (A)	
	. Treatment Train (Check components that appl	y)
	☐ Metals removal ☐ Oil/water separation	☐ Bioremediation
	☐ Air stripping ☐ Carbon adsorbers	
	Filters	
	☐ Filters Additive (e.g., chelation agent, flocculent)	
	Others	
	☐ Others Needs Maintenance	
	☐ Sampling ports properly marked and function	
	☐ Sampling/maintenance log displayed and up	
	Equipment properly identified	to date
	Quantity of groundwater treated annually	
	Quantity of groundwater treated annually	
	Quantity of surface water treated annually _	
	Remarks	
	the second control of the second seco	
2	. Electrical Enclosures and Panels (properly rat	
	N/A ☐ Good condition	☐ Needs Maintenance
	Remarks	
3	. Tanks, Vaults, Storage Vessels	
	⊠N/A ☐ Good co	ndition
	☐ Proper secondary containment ☐ Needs M	
	Remarks	500 TO 100 HOLD 100 TO
4	. Discharge Structure and Appurtenances	
	☑N/A ☐ Good condition	
	Remarks	
5	. Treatment Building(s)	
	N/A ☐ Good condition (esp. r	oof and doorways) Needs renair
	Chemicals and equipment properly stored	oor and doorways) 11ccas repair
	Remarks	· · · · · · · · · · · · · · · · · · ·
1.02		
6	. Monitoring Wells (pump and treatment remedy	
	☐ Properly secured/locked ☐ Functioning	☐ Routinely sampled
	☐ Good condition ☐ All required well	Is located Needs Maintenance
	XN/A WAS NOT PART OF ATRE	HTMENT SYSTEM CODII
	Remarks One abandoned well	tocation was 9/16/13
	observed on site. Bentomit	c used. (2) 9/16/13
D A		
	Nonitoring Data NOT APPUCABLE . Monitoring Data	
	☐ Is routinely submitted on time	☐ Is of acceptable quality
-		☐ is of acceptable quality
2	. Monitoring data suggests:	Conteminant appropriations are
	☐ Groundwater plume is effectively contained	Contaminant concentrations are
		declining

Site Name: Sitt 7

JACOBS Five-Year Review Site Inspection Checklist (11/12)

E. Monitoring Natural Attenuation
1. Monitoring Wells (natural attenuation remedy)
☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled
☐ Good condition ☐ All required wells located ☐ Needs Maintenance
DN/A
Remarks One abandoned well location left 9/13/13
observed ensate
X. OTHER REMEDIES
If there are remedies applied at the site which are not covered above, attach an inspection sheet
describing the physical nature and condition of any facility associated with the remedy. An
example would be soil vapor extraction.
XI. OVERALL OBSERVATIONS
A. Implementation of the Remedy
Describe issues and observations relating to whether the remedy is effective and
functioning as designed. Begin with a brief statement of what the remedy is to accomplish
(i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).
The Remedy at Site 7 Cargo beach Road
landfill was intended to place a 2'capover
the landfill and implement land use controls.
The selected Remidy is effective in general.
The cap remains in good condition however
debyis was noted along the perimeter. There
was a small amount of debris proteuding
from the cap on the southiren side near
the apmored rock. Debris was also observed in
the near by ponds.
B. Adequacy of O&M
Describe issues and observations related to the implementation and scope of O&M procedures.
In particular, discuss their relationship to the current and long-term protectiveness of the
remedy.
Site 7 has been graded to promote positive
dearnage and mitigate experion.
A PART TO SEE THE SECOND SECON
-
12 AND THE RESERVE OF

JACOBS Five-Year Review Site Inspection Checklist (12/12)

C. Early Indicators of Potential Remedy Problems
Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs that suggest that the protectiveness of the
remedy may be compromised in the future. NONE OBSERVED.
D. Opportunities for Optimization
Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.
Add additional fill to the southern side of the cap to ensure a 2'cover. Remove
additional debris remaining outside of
cap including a few susted of 55gal drums.
Implement LUCS, Obtain 18 AAC, 75.350
Tormal documentation Jappional

The Dallolis

pas - SSG deulns
post - Schredings

Outdoor writing products of for Outdoor writing people



This cover contains post-consumer recycled material

- Rite in the Rain

A patented, environmentally responsible, all-weather writing paper that sheds water and enables you to write anywhere, in any weather.

Using a pencil or all-weather pen. Rite in the Rain ensures that your notes survive the rigors of the field, regardless of the conditions.

J. L. DARLING CORPORATION Tacoma, WA 98424-1017 USA www.RiteintheRain.com

> Item No. 373 ISBN: 978-1-932149-87-6

Made in the USA US Pat No. 6,863,940



NECAPE 5-4R REVIEW LOGBOOK # 1 SITE NOTES

9/11/13 70 9/16/13

ALL-WEATHER

UNIVERSAL

Nº 373

C. FELL J. ORCZEWSKA K. MAHER


HTRW-JO7-05F45902-HOH-0001 OSF45902

Did you remember ... ???

collected)

Daily Logbook Checklis	<u>t</u> .
Project name / Site ID / Client	
Date	
Weather, site conditions, and other sal	ient
observations	
Level of PPE used	
Full names of onsite personnel and aff	filiations
(including all visitors)	
Daily objectives	
Field measurements and calibrations	
Time and location of activity	
Field observations and comments	
Deviations from the Work Plan	
Site photographs	
Site sketches (with reference i.e. "N"	arrow)
Survey and location i.e. samples or de	bris (GPS
coordinates when possible)	
For each sample record:	
Date, time, sampler(s)Sample ID	
– Sample ID – Media,	
container(s),	
preservatives	THE
- QC	
(dup/MS/MSD)	B
- Analysis	//AHH
- MeOH lot #	And Artificial Control of the
- Tare weight	
Sample shipments (when, what, desting	nation)
Waste tracking (when, how much, des	

Daily summary of activities (i.e. # of samples



Rite in the Rain — A patented, environmentally responsible, all-weather writing paper that sheds water and enables you to write anywhere, in any weather. Using a pencil or all-weather pen, Rite in the Rain ensures that your notes survive the rigors of the field, regardless of the conditions.

RiteintheRain.com


	CONTENTS	
AGE	REFERENCE	DATE
1-3	DAY 1: SITE SETUP	9/11/13
	DAYZ: SAMPLING ACTIVITES	9/12/13
	DAY3: SITE 32 SITEWALK (TRANSMENT)	9/13/13
	DAYBISITE 31 SITE WALK (WHES)	9/13/13
	or a series	9/13/13
	DAY3: SITE 9 SITEWALK QUERTIENS LAW DELL	9/13/13
11 1	DAY4: SITE I SITE WALK (AIRFIELD)	9/14/13
	DAY 4: SITE 3 SITEWALK (FUEL PUAPHONE)	
	DAYHISITE G SITE WALK (GRAVEL)	9/14/13
191.5	DAY4151TE 29 SLITE WHILL (SUQIADOGHNED)	9/14/13
-161	DAY 4:SITES SITE WALK (POL SPILL)	9/14/13
	DAY 41 SITE 10 SITE WALK (BURIED DRUMS)	9/14/13
	DAY 4: SITE II SITE WALK (FUEL DAWICS)	9/14/13
	DAYSISITE 28 SITE WALK (DEHWAGE BASW)	9/15/13
	DAYS ISITE 20 SITE WALK (WASTEVATEL TANK	11
	/ sole \	9/15/13
		9/15/3
8	DAYS: SITE 13 SITE WALK (HEAT & POWER PLANT)	9/15/13
70	SITE IS SITE WALK (FUEL PIRELINE)	9/15/13
52	SITE 19 SITE WALL (AUTO MALDITENANCE)	9/15/13
	SITE 27 SITE WALK (DIESEL FUEL PUMP)	1 / -
55 56-62	DAY 61 DEMOBIL & USACEOUSITE LUTERLINEW PHOTOLOG & WASTE TRACKING	9/16/13

1240 L							(R
NEC		N AT E	KIOIO	U LA	0.017	G CV.	1
70 E C	MY IZ		() ()				1
SITE	DRIE	UTATO)	u cul	CHO	CK CRÓ	DIFU	27
	JK-10.	o milos		<u> </u>			01.20
PERSO	NNEL	(LEVI	EL DP	PE)		1 1	
	10	K. MAI			P.M.		11
		J. OR			Block	X157	10 10 7 5 20
JAC	OBS	CFEL	L		Geac	GIST	, a
8245	TOL	C. CR	OLEY		SITE	SUPER	
USA	CF	J. Ch	INER		QAR	(f a) =	(10) (0) (10)
						14	
1430 60	OT SITU	HTED 1.	N LOD	GNG	AND P	REPLED	
		F THE					
		ICE 1	100				
					> SACE	ISSUE	-?
5-	- 1						
10 PI	AN TO) SEW	O RFM	ALNOE	e of s	7+4	-
					HGG ING		106
	CATIO		23 710	7 10	100.100		
	SAIO	03					i
14/X!	More	LY CLO	201.	- D.F	PEART	1 1	7
	1,1021	1 0	707 10) Wa	cup mid	14.00	1) ()

NE CAPE NECHPE USACE S-YR REVIEW 5-YR REVIEW 9/11/13 USACE SITE DRIVE W/ THE CRAR (USACE) 1521 LOSTITE 16 IS ESSENTIALLY AT THE GAC STATION JUST BEFORE THE GAC STATION DISITE 8 IS THE LOW LYING AREA ALONG I DIRECTIONS ARE BASED EN COMING FROM CAMP THE RIGHT SIDE OF THE ROUTD (CAMP) 1742 END OF SITE WALK LOSITE 7 IS THE THICK VEGETATED HILL LEFT FROM SITES ARE STAGED 1745 DINNER TO 1915 45 TE 3 15 OW THE RIGHT JUST BEFORE BEXIN GEAR ORCANIZATION & COSLER PRED 1820 45ITE 4 IS ON THE KEFFT JUST BEFORE BEACH From WP Battle Count SITES IS ON THE BEACH 2519 Coolers = 12 • Flergl NOTE MARK BOUNDARIES OF SITES WHERE 250 HNO2 Polys = 33 30 1 L Hac = 35 OBSERVED OR MAKE SKETCHES 30 1 L No pres = 1240 50 45 YOUL HELL NOA = 88 60 1612 , LISTE 9 IS THE BARR ALEA ON LEFT SIDE OF ROAD JUST BEFORE INTERNOOM CONTMUTE Per cooler Sombe logation STABING AREA ON THE RIGHT GROUND WATER + SW 7 SITE 10 IS THE NEWLY GRADED AREA JUST PAST - 6x 40ml von CONTAINER STAGING AREA. - 2 - IL Hel pager SITE 11 IS THE NEWLY DISTURBIED ALEA JUST - 3 x 16 No pus a some DOWN HILL OF THE CEPING SITE IO -2 x 250 nc HNO3 FRituR 13 SITE 28 IS THE LOW AREA BELOW SITE 10 LASSITE 31 232 ARE UP THE ROAD TOWARD QUARRIES 2005 END OF DAY 932 IS FOUNDATION AT BASE OF HILL Scale: 1 square = 1 1 1 1 1 PAGES PAGE 2 Scale: 1 square = ____


NE CAPE USACE NE CAPE 9/12/13 9/12/13 S YEAR REVIEW 5-YEAR REVIEW 0655 HEALTH AND SAFETY MEETING (BRISTOL) 0754 TURBIDIMETER (5/1 6192) GRALIBRATED ON 9/6/13 BYTTT ENVIRO 0715 DAILY TAIL GATE (JACOBS) YSI (5/N 100449) CALIBRATION VERIFICATION 0905 PERSONNEL (LEVEL D PPE) LACALIBRATED ON 9/6/13 BYTT EVUIRO LA BAROMETER CAL: 29.72 in Hg JACOBS K. MAHER SITE LEAD JACOBS C. FELL SSHO/TECH LICAL WERIFICATION -ORP: 240mV exp. 12/17 = 256.8mV OK JACOBS J. ORCZEWSKA TECH 7 COND: 1413 um cm/1020um/cm=9290K > pH7.0: 6.95 -> pH 10.01: 10.01 OK 7 pH 4.01: 3.95 OK WX: PARTLY TO MOSTLY CLOUDY 35°F TO 405F 0940 LOADED SUPPLIES IN PICKED AND CALM TO LIGHT BREEZE TRAVELLED TO SITE 9 DAILY OBJECTIVES: 0945 ARRIVED AT SITE 9 LANDFILL 0752 - CONPLETE GW/SUFACEWATER SAMPLUS H BEGAN SAMPLING PROCEPURE AT -SITE WALKS FOR SITE 7 \$9 (LANDAIL) LOCATIONS 94-WSOI \$ GLF-WS02 Mesta 1213 0950 ADVANCED DRIVE POINT PAGE 4 Scale: 1 square = PAGE S Rite in the Rain Scale: 1 square =

NE CAPE USACE NE CAPE USACIE 9/12/13 S YEAR REVIEW 9/12/13 S YEAR REVIEW * SAMPLE: 13-9LF-WSOI-0 BEGAN SAMPLING PROCEDURE AT 1000 PRIMAPY LOCATION 9LF-SW03 LACOLLECTED WITH DEDICATED DIPPER L9 4 40ml VOAS (HCI) AKIOI /BEEX SWEEGO 1155 SW7471 MERCURY SW7471 MERCURY 250poly (HWO3) SUFORD REPAIRS
250poly (HWO3) RURA METALS *SAMPLE: 13-9LF-WS03-0 unfiltered La 1x KN/70 LACOLLECTED WITH DEDICATED DIPPER a | xw/20 VOAS (HCI) AKIOI/SUBZEO L72 IL AMBER/HCI) AKIOZ/AKIO3 SWEDZO RCRAMETALS SW7471 MERCURY infiltered 43 (LAMBER (none) SW8270 SIM / SWE082 250 poly (HAD3) SWGOZZ - SURFACE WATER filtered MERCURY 42 IL AMBER/HU AKIOZ/AKIO3 - FILTERED METALS COLLECTED W/ PERISMLTIC 43 1 LAMBER (none) SUBZ70 SIM /SW8082 - 9 SURFACE WATER * SAMPLE: 13-9LF-4502-0 - FILTERED METALS COLLECTED W/PERISTALTE LOCOLLECTED WITH DEDICATED DIPPER FINISHED SAMPLING AT LOCATION 174 40 M WAS (HCI) AKIOI/BTEX SWEZED SW 7471 NERCURY SW 7471 NERCURY 250 poly (HAD) SWGCZO RCFLMEMIS 250 poly (HAD) SWGCZO 250 poly (HAD) RCEL METMIS 9LF-WS03 unfiltered filtered 250psly (HNO3) Ly ZIL AMBER (HCI) SAMPLING LOCATIONS ARE 1212 43 1L AMBER (nov.) SW8270151M /SW8082 RECORDED DN APPENDIX A FIGURES - TSURFACE WATER - FILTERED METALS COLLECTED W/PERISMETIC IN THE WORKPLAN (FIELD COPY) AND ON PAGE 8 1135 FINISHED SAMPLING 9LF-WSOI 9LF -WSOZ 1215 LEFT FOR LUNCH SAMPLES MAINTAINED AT 4±2°C APTER COLLECTION PAGE 7 Rite in the Rain. PAGE6 Scale: 1 square = ____ Scale: 1 square = 2



NE CAPE NE CAPE USACIE ISACE 9/12/13 9/19/13 S YEAR REVIEW S YEAR REVIEW GROUNDWATER GRAB SAMPLING AT 1516 STARTED SIMPLING PROCEPURE 1437 LOCATION 9LF-WGOI AT THE KANGUKSHAM MOINTAIN - WATER EXTREMELT TURBIO W/ SPRING. SILT/ANESAND & ORGANICS. 1521 *SAMPLE: 13-KMS-WSO1-0 - SCREEN CONTINUALLY PODGS WITH FINE ORGANIES & SEDIMENT S COLLECTED WITH DEDICATED DIRPER, BEI WASA FILTERED W/ EDGILE METALS COLLECTED - PRODUCTION RATE MUCH LOWER CF/10 THAN 250ml/min WITH PERISTALTIC PUMP - 4 40 ml was in one Hour LA 40 ml VOAS (HC) AKION SWBZEE (BJEX) 17 | 250m Pay (MO) RERAMETALS MERCERY LT | 250m POLY (HNO3) RICH METALS MELLEY 1450 FINISITED SAMPLING 9LF-WSO4 LTZ IL AMBER (HCI) AKIOZ/AKIOS 504 ARRIVED AT KNGUKSHAM MOUNTAIN 43 IL AMBER (none) SW82705111/5W8082 SPRING SAMPLING LOCATION (KMS -> SURFACE WATER 1539 FINISHED SHAPLING AT KANGUKSHAM MOUNTAW SPRING MINI FALL 1000 ISSO FINISHED SAMPLING AT CILVERY 9LF WEG (CF) 9/12 11.5 9LF-WGOI- 2 OUR TO EXTREMELY LOW WATER PRODUCTION FROM THE WELL POINT Scale: 1 square = PAGE | Rite in the Rain Scale: 1 square = PAGE 10

NE CAPE USACE NE CAPE USTOR 9/12/13 S GEAR REVIEW 9/12/13 5 YEAR REVIEW 644 * SAMPLE: 13-7LF-WSOZ-0 1600 ARRIVED AT SITE ? CANDFLL 5 COLLECTED W/ DEPICATED DIPPER GILAD OUT LOCATIONS FILTERED METALS COLLECTED WITH STARTED SAMPLING PROCEDURE AT PERISTACTIC PUMP 1625 674 HOM VOAS (HU) AKIOI/SW826D(BIEX 7LF-WSOI SWECED RORLAND FILTERED LA 1 250ml POLY (HUD3) SWEDZO RCRAMETALS SW7471 MERCURY UNFILTERED LAI 25anl AULY (HUO) 1630 *SAMPLE! 13-7LF-WSOI-0 GCOLECTED W/ DEDICATED DIPPER, L72 (LAMBER (HCI) AKIOZ/AKIO3 LA3 (LAMBER(none) SW3270 SIM/SW 8082 FILTERA METHUS COLLECTED W/ ->SURFACE WATER PERISTALTIC PUMP tom VUHS (Hel) AKIOI/SUSEGO (BTEX) SW 7471 MERCUL 1 FILTERED IS 1 250ml POLY (HNO) SWEDOW RERAMETALS 1653 STARTED SAMPLING PROCEDURE AT UNFILTERED IN 1 250 A POLY/HADZ RCRA METALS MERCULY 7LF-WS03-0 AKIOZ/AKIO3 42 IL AMBER (4C1) 43 | L AMBER (none) SW827051M/SWED82 1654 *SAMPLE: 13-7LF-WS03-0 - SURFACE WATER ORIMARY LACOLLEGIED W/ DEPICATED DIPPER, PILTERED NETALS JOICE LATE 11 1 DERISTALTIC PUMP FINISHED SAMPLING AT 7LF WSOI 650 40ml VOAS (HCI) AKIOI/SW8260 (BTEX) 250m POLY (HNO3) SWEDZE REA METALS STARTED SAMPLING PROCEDURE AT FILTERED LOS 1 RCRA WETALS CWFILTERED LT 250ml POLY (HNO3) 7LF-WS02 11_ AMBER (HCI) 125 AK102/AK103 1 LAMBER (none) SWERTESIM/SWEEDSZ -> SURFACE WATTER Scale: 1 square = PAGE 3 PAGE 12 Rite in the Rain Scale: 1 square =



USACE NE CAPIE NE CAPE USACE S YEAR REVIEW 9/13/13 9/13/13 5 YEAR REVIEW ONTOO JAROBS TAILGATE PREPEARED CHAWS OF CUSTODY 0830 PERSONNEL FOR & COOLERS WITH 1140 SAMPLES COLLECTED ON JACOBS KIMAHER SHELEND SSHO/TECH 9/12/13 JACOBS CIFFIC JACOBS I ORCZEWSKA TECH COOLERS -KILO T K, MAHED DEPARTED AT APPROX 1440 - YOLIETT - CHARLIE WX WINDY 10-20mph GUSTS - MIKIE 305F TO 405F - ALFA OVERCHST - HOTEL 0720 DAILY OBJECTIVES - ECHO - COOLER PACKING - ROMEO - RENTAL DEMOBIE 1140 SYEAR REVIEW CHECKLIST - 5 YR REULEW TRAINING -BEGIN SYR REVIEWS TRAINING 1200 LUNCH (1800) BRISTOL TAILGATTE 1230 BACK FROM WUNCH-GOING TO START SITE WALKS TK. MAHER WATTING W CAMP ROR AIRPLANTS TO NOME PAGE 16 Scale: 1 square = PAGE 17 Rite in the Rain. Scale: 1 square =

NE CAPE USACE NE CAPE 5 YEAR REVIEW 9/13/13 1240 SITE WALKOF SITE 32-LOWER TRANSMY 57SEE CHECKLIST FOR FURTHER INFORMATION SITE 32 LOWER TRAINWAY BORROW PIT. N.T.5. Krow Culy EROSION/ MINUR SETTLEMENT POUNDATION <0 APPARE UT GROUNDONNER () PICTURE LOCATION PHGE 18 Scale: 1 square =

9/13/13 S YEAR REVIEW 1313 OBSERVED MINUR WOOD AND METAL DEBLIS ON SITE 1321 OBSERVED MINOR ASPHALMS SHWELE DEBRIG 1x2FT TO 2x2FT (APPROX) DIMENSIONS ON THE GROUND WEST OF THE ULD FOUNDATION 1325 OBSERVED APPARENT GROWN DISTURBANDE (RECENT) TO THE EAST OF THE OLD FOUNDATION. THIN VEGETATION IS GROWING ON THE EXPREMELY ROCKY SOIL 1327 NO GROUNDWATER MONITORING WELLS WERE OBSERVED 1330 CULVERT UNDER ROAD AT THE SITE IS APPROL 5 TOG PT IN DIAMETER 1332 ONGOING REMEDIAL ACTIVITY IS MINIAG BORLOW FOR BACK FILL ADJACENT TO THE SITE ON THE COPOSITE SIDE OF KANGUKHSAM MOUNTAIN SPRING 1343 LEFT SITE 32: LOWER TRAMWAY Scale: 1 square = PAGE 19 Rite in the Rain.

USICE


NE CAPE USLEE NE CAPE USACE . 9/13/13 SYEAR REVIEW 9/13/13 5 YEAR REVIEW 1404 OBSERVED MINOR WOOD/METAL/WILLING DEBRIS WEAR 1347 ARRIVED AT SITE 31 : FORMER WHITE ALICE ANTENNA FOUNDATION "C" SITE 31: FORMER WHITE ALICE, 1405 OBSERVED A DRAIN COVER (RUSTED) ON THE SOUTH-SIDE OF FOUNDATION 'E" WITH AN UNFILLED VOID UNDERNEATH (APROX 6 FT DEEP, S WIDE, 9FT LENGTH) WELL VEGETATED DRAIN IS APPROX 4FT LOWIN & GINCHES WIDE. N.T.S. B (REALLY FORTHER 1415 APEN AROUND FOUNDATION "E" AND ANTENNA FOUNDATION "4" EAST THAN SHOWN) HAVE BEEN RECENTLY GRADED, CONPACTED, AND SEEDED, NEW VEGETATION IS JUST SPROUTING RECENTLY GEADED AREA APPEARS TO BE GLYDED TO PROMOTE POSITIVE DEALWAGE AND MITIGATE ERUSION NEW DRAIN AGE 1416 HOLES IN POUNDATIONS HAVE BEEN FILLED WITH SOIL DITCH LONO STAINING OF CONCRETE OBSERVED 1420 AREA OF STUNTED VEGETATION OF SIE UPHILL VEGETATION (TOPMES STRUCTURE?) FROM THE WASS SITE (APPROX 209T BY30FT RECTANGLE 1424 NO GROUNDINATER MONTTOLING WELLS OBSERVED A FOUNDATION (CONCRETE) 1440 LEFT SITE: 31: WHITE ALICE (1) => PHOTO + DIRECTION SCHECKLIST ON SEP BRATE FORM 12 HOLES IN FOUNDATIONS (PILLED W/ SOIL) Scale: 1 square = PAGE Z PHGE 20 Rite in the Rain. Scale: 1 square = ____

NE CAPE NE CAPE USACE USACE 9/13/13 9/13/13 5 YR REVIEW 5 YEAR REVIEW 1517 THE LANDFILL COVER APPEARS TO CONSIST OF 1509 ARRIVED AT SITE 7: CARGO BEACH ROAD LINDFILL FINE AND COARSE GLAVEL AT THE SURFACE WITH SITE 7: CARGO BEACH ROAD LAWDFILL ! PATCHY GRASS COVIER 1523 CARGO BEACH ROAD CROSSES THE CANDFILL CAP. NO STETTLEMENT OBSERVED GRADING/DRAINAGE APPEARS ADEQUATE N NITS 1528 WOOD DEBRIS AT PICTURE OLOCATION (MINOR) 00 WITH OTHER WOOD AND METAL DEBRIS NEARBY ANDELL (BANDONEO 1546 OBSERVED 2 RUSTED OUT DRUMS WEAR THE EDGE OF THE METAL X PUND NEAR THE NE CORNER OF THE LANDFILL (5500) ?) DEBAIS N POND 1547 OBSERVED METAL/WOD/PLATIC DEBRIS IN THE NORTHEAST POUN 1552 OFFERNED METAL DEBRIS IN THE POND AT THE NW GRUER OF THE LANDFILL WINERE ACTURE (S) WHO TAKEN CARGO BEALLY SWAMP AFFA 1553 LANDFILL CAP DOES NOT HAVE OBSERVED SIGNS POND. OF SETTLEMENT /EROSION OR LANDFUL DEBRC SHOULD BE FURTHER STICKING THROUGH THE CAP APPROX: THATWAY LANDFILL BOUNDARY 1559 OBSELVED METAL DEBLIS IN THE POND TO THE WEST OF THE LANDFILL (METAL ROOFING?) - PICTURES 647 X LANDFILL BOUNDARY (AFROX) TIT STEEP SLOPE DO-7 PICTURE LOCATION & DIRRUTION Scale: 1 square = PAGE ZZ Scale: 1 square = PAGE 23 Rite in the Rain.

NE CAPIE USACE NECAPE 1)SACE 9/13/13 9/13/13 5 YEAR REVIEW 5 YEAR REVIEW SITE 9: HOUSING & 1607 RUBBER HOSE STICKING THROUGH LANDFILL CAP OPERATIONS LANDFILL ALONG WITH SOME METAL DEBRIS NEAR PICTURES 10 \$11 1615 OPSERVED AN ABANDONED MONITORING WELL WEAR THE SE CORNER OF THE LANDFILL-ABANDONED N.T.S. PAND WITH HYDRATED BEMOUTE 1616 OBSERVED MINOR METAL DEBRIS AND OTHER DEBLIS -> ADND LANDFILL IN THE POND NEARTHE SE CORNER OF THE LANDSTA LTOBSERVED A SUBMERGED OBJECT W/ A ROUND CAP? OPENING (DRUM? ABWAWED MUNTACINE 1633 TITEMS OF INTEREST A - DEBRIS PROTRUDING THROUGH CAP ON SSIDE (MINOR) PUND! - SIGNIFICANT METAL & WOOD DEBRIS IN THE SURROUNDING PONDS (INCLUDING AFEN RUSTED OUT DRUMS DO > PICTURE LOCATION & DIRECTION 1637 LEFT SITE 7 LANOFILL () POND BOUNDARY LASYR REVIEW CHECKUST ON SEPERATE FORM --- DIVERSION DITCH > CULVERT 16400 ARRIVED AT SITE 9: HOUSING & OPERATIONS LANDFILL 1642 DRAINAGE IN EXCELLENT CONDITION -195 YA REVIEW CHECKLIST INCLUDED ON NO VEGETATION IN DITCH A SEPERATE FORM Scale: 1 square = PAGE 25 Rite in the Rain. PAGE 24 Scale: 1 square = ____

NE CHOE USKUE USACE NE CAPE 9/13/13 9/13/13 5 YEAR REVIEW S YEAR REVIEW 0800 BRISTOL THEGATE 1649 LANDFILL CAP APPEARS TO BE IN GOOD CONDITION WITH THINGRASSY MEGETATION. CAP IS CONDOSED OF COARSE MATERIAL JACOBS TAILGATE 0830 (GRAVEL) THAT MAKES VEGETATIONS GROWTH PERSONNEL DIFFICULT. SHOBS CIFELL SITELEAD 1651 ELOSIAN & SETTLEMENT WERE NOT JACOBS J. ORCZEWSKA SSHO/TECH OBSERVED, GRADING APEARS TO ALLOW DRAWAGE 1657 OBSERVED AN ABANDONED MONTERING WELL AT THE SW CORVER OF THE OLD LANDFILL CAP. WX2 CALM 305 TO 405F GCOULD NOT FIND THE OTHER 2 MONTORING OVERCAST WELLS SHOW IN THE DECISION DOCUMENT 250 DAILY OBJECTILLES 1734 LEFT SITE 9: HOUSING & OPERATIONS LANDFILL - 5 YEAR REVIEW SITE WALKS - PAPERLWORK QC ENO ONE DAY - CONTINUE PREP FOR DEMOBE 850 SITE HISTORY REVIYEW PAGE 26 Scale: 1 square = PAGE 27 Rite in the Rain

Scale: 1 square =



NECARE	NE CAPE	USACE
5 YEAR REVIEW 9/14/13	5 YEAR REVIEW	9/14/13
1014 AFFW SHIPMUG RACKS ARE STAGED ON THE FUND	1055 ARRIVED AT SITE 3: FUL	EL PunflicisE
STATE RUNWAY AT THE WWITER STORAGE AREA	5ITE 3: FUEL PU	
033 MINOR WOOD OFFRIS NOTED ALONG THE EAST SIDE	• 4	SEA
OF THE RUWLY NEAR THE NORTH END	3	BEACH
	N	
138 A TRAIL HAS BEEN FORMED OFF THE WRITH END OF	nitos.	
THE RUNWAY LEADING TO THE BEACH.		
	• //	
044 LEFT SITE I ARSTRIP		
LOS YEAR REVIEW CHECKUST ON A SEPERTTE FORM & COTY	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	•
	The state of the s	
TTEMS OF INTEREST	DAY LYWG	
- MINOR SLOPE STABILITIES ISSUES ON THE	D (D) (HEED MC?)	
RUNWAY FOGES.	SHEEN (PERPOCENIE?)	
		1: N 2
	• //	
	/40	
13	MIRFIELD	
y for a give	9	
M. Chica		60 8 14 1/1 65 0 6 6 6 76 6 16 16 16
		D: (0.1 0 00 00 00 00 00 00 00 00 00 00 00 00
icale: 1 square = PAGE 30	Scale: 1 square = PAG	E31 Rite in the Rai
Scale: 1 square = PAGZ 30	Scale: 1 square = PAG	72 31 Rite in the

NE CAPIE	USACIE	WE CAPIE	USACE
5 YEAR REVIEW	9/14/13	S YEAR REUNEW	9/14/13
12 OBSERVED 4 SALVACED PLECTE OF RUSTI	ED OUT	SITE 6: G	RAVEL PAD
EQUIPMENT STAGED FOR REMOULL	* * * * * * * * * * * * * * * * * * *		0 0 A 2 E E 0 0 0 0 K 0 0 C 0 0
13 EXCAVATION AREA NOTED IN THE ROO A	PREARS TO		21000 LITER FUEL TAUKS
NOW BE AROND		N 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	21.597.06
	•		CONTINUES SHAPING STA
14 BIOGENIC SHETN (BRITTLE) NOTED ON S FROM THE ROAD	SOME WATER W		SRAVED B SHA
16 FORMER PIPELINE WAS NOT OBSERUE	O (REMOVED?)	3	.60 5 / / / / / / / / / / / / / / / / / /
FORMER PUNCHOUSE STRUCTURE HAS BE	STATE OF THE PARTY	914	A COUNTY OF
		9114	Abrum
19 SHEEN NOTED ON PONDED WATTER WEAR	THE CRAVEL		MONIME & 19 SHIRDING
PAP. SHEEN WAS NOT BRITTLE AND F	COWED BACK		CONTAINERS
TOGETHER AFTER BEING DISTURBED	(LIGHT SHEEN)	LANDFILL	
1			
26 VEGETATION IS GLOWING WELL	ONSITE	SITE 7	
EXCEPT ON A NEW GRAVEL PAD			
32 LEFT SITE 3 : FUEL PUMPHOUSE			
			1
33 ARRIVED AT SITE 6: GRAVEL PAD			
5 YEAR REVIEW CHRCKLIST ON AS	SERLATE FORM	GRAVEL PAO	
		ABANDONED MOUNTAING I	
		OOP PHOTO LOCATION, DIRECT	now
cale: 1 square = PAGE 32		Scale: 1 square =	PAGE 33 Rite in the Rai

NE CAPE	USACE	NE CAPE	USACTE
5 YEAR REVIEW	9/14/13	5 YEAR REVIEW	9/14/13
1140 OBSERVES AN ABRUDANED MONTORING CHELL	ON THE	1341 SITEWALK FOR SITE &	
SW SDE OF THE SITE. (HYDRATED BENTON	TITE)	575 YEAR REVIEW CH	ECICLIST OW X
		SEPERATE FORM.	
143 A SECOND ABANDONED MONITORING WELLOB	SELVED ON		
THE WEST CORNER OF THE PAD HYDRAY	TEO BENTONITE)	SITE 29: SUQITUGHA	VEQ RIVER
			E
148 DID NOT OBSERVE STAINING ON THE	MEWLY	A AIRFIELD	04
GRAPED GRAVEL PAD THET IS CURREN	U 764	1/25	PIC TAKEN LOOK IN
BEING USED TO STORE SHIPPING CONTA	18. A.	N CAMP ST	
		n.t.s.	A B
LAPAD APPEARS TO HAVE BEEN RECENT	LY SAMPLED		1 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -
5 (DID SAMPIING	•	S/June CAME	ROAD
HPAD GRAPED TO PROMOTE DRAWAGE AND MI	MIGHTR SLOSION	S Cunto	
1153 OID NOT OBSERVE DEBRIS OR A SHEEN 1	N THE BUD		
TO THE SOUTH OF THE SITE		CP9/14	CHGO BEACH ROAD
		MALKED	
1155 LEFT SITE 6: GRAVEL PAD	•		
		ally Vite 25	
1206 LUNCH		RIVER GHNEG STREW	
	•	STREAM WALL	
230 DONE WITH LUNCK	C	TO 1/	20 4
		LOWEL /	WE .
1230 VIEWED HISTORICAL PHOTOS U	WITH		FLOW
1340 JEREMY CRANER (USACE)		OF GR PHOTO, DIRECTION	
10	•	Scale: 1 square =	4SE 35
Scale: 1 square = PAGE 34		Scale: 1 square =	HGB 35 Rite in the Ra

NE CHAIE NE CAPIE USLEE USACIE 9/14/13 9/14/13 5 YEAR REVIEW 5 YEAR REVIEW 1352 WALKED THE SURITUGHNER RIVER FROM 1450 WALKED THE SURDITUGHNED RIVER FROM CARGO BATCH ROAD UPSTREAM CAMP ROAD TO THE ESTUARY LAWATER HOSE (HING) IN THE WATER AT THE (PEHLOCENIC) CULVERT FOR CARGO BEACH ROAD, MAY BE IN 1357 DIPNOT OBSERVE ANY DEBRIS OR SHEEN, LOOKS LIKE USE AS A WATER SOULCE FOR CONSTRUCTION A RIVER REMEDIATION ACTIVITIES 1402 CONSTRUCTION CAMP IS PUMPING WATTER FROM THE ISOU DID NOT SEE DEBRIS/SHEEN (PETROGENIC) ALONG THE SURITURAL NEED RIVER FOR GENERAL USE (SOUTH OF ROAD) SUQITUGHNEQ RIVER 1411 WAKED THE SUBTRUGHNED RIVER FROM CAMP ROAD TO THE 15/2 LEFT SITE 29: SUQITUGHNED RIVER END OF THE RUNWAY 1412 OID NUT OUT OUTFUT CERTIN ANY DEBRIS CR 1515 SITE WALK FOR SITES: POL SPILL LASYER CHECKLIST ON A SEPERATE FORM SHEEN (PETROGENIC). TRAVELLED UP RIVER 1522 VEGETATION IS THICK AND HEALTHY NO ODOR OBSERVED NO SHEEN (PETROGENIC) OBSERVED 1426 WALKED THE SURITUGHNER PROM NO DEBRIS OBSERVED CARGO BEACH ROLD TOWNRIPS THE MIRFIELD 1533 LEFT SITE 8: POL SPILL 1433 OBSERVED A DRUM IN A POND - VERY RUSTED, NO SHEEN OBSERVED. 1495 DID NOT SEP DEBRIS/SHEEN (PETROGENIC) TO NOVITH OF SITE 28 DEALWEE Scale: 1 square = PAGE 37 PAGE 36 Rite in the Rain.

Scale: 1 square = ___

NE CAPE	USACE	NE CAPE	USTEE
5 YEAR REVIEW	9/14/13	5 YEAR REVIEW	9/14/13
SITES! POL SPILL	<i>-</i>	1534 ARRIVED AT SITE 10: BI	PRIED DRUMS
A		55 YEAR REVIEW CHEC	ILLIST ON A SEPERATUR FORM
h			
AIR AIR	FIELD ARCO	SITE 10: BU	RIED DRUMS
N EST AIR	TO CARCO		(3)
nts /g/			(BURGUED)
11/3			MENTICALING TO MANY MANY MANY MANY MANY MANY MANY MANY
		(3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	ZET DIAMETED SHEME
1 / 2010		N n.t.s.	NTER MODAL
		- 6 TEX / 6	WIER MODIL CHITAINERS & MANNIN
1000 800	1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- I wie	
and 8			DRUM
1,20		32	M
40	•		00HD 7
76		CAGO DEACH	(4)
The second second		3	
Dist Flav	Q1TUCHMED		
40//	MEG		
		01-01-01-01-01-01-01-01-01-01-01-01-01-0	
11/ <101 000 4054		PHOTO, DIRECTION FACIN	
SWHAPY AREA	(05C7) A. I. S. L	INTERMODAL CONTAINER	
= CULVERT DAYLIGHT (1) → PHOTO, A Scale: 1 square = PAGE 3	RECTION FLEING	Scale: 1 square =	


NE	CAPE	5ACE	NE CAPE	USACE
5	TEAR REVIEW 9	14/13	S YEAR REVIEW	9/14/13
1547	OBSERVED WOOD AND WETAL DEBRIS (MINOR) A	TTHE S	SITE 11: FUEL TANK	5 /
C .	NE CORNER OF THE SITE		A \\	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1	X 0		4	1-
15500	OBSERVED MONITORING WELL (O-1, WELL			
1	HAS JACKED FOOT ABOVE THE PROTECT		N (2)	1/
1	STEEL CASING, NO LOCKING CAP OR P	ROTECTIVE -	N.T.S.	\'\\\\
	BOLLAROS.		7 GRADED	
1554	EVIDEN BY GIVE OBERVED EVIDENCE OF	PERENT	Aus	
1227	SOIL BORINGS & SAMPLING ACTIVITY	Action 1	SEDED	
1 0			1	
1558	SITE IS CORPEUTLY BEING USED AS A LAY	Doun	3 mw 3	
	AREA BY THE REMEDIAL CONTRACTOR (BRISTO		9 80-3	
	SITE IS GRADED AND COMPLETED TO FROM	OTE CO		*
4	POSITIVE DRAWAGE AND MITIGHTE EROSE	w .	1 1 9	
	1			\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \
	NO VEGETATION PRESENT ON THE GRAVEL			70/
I I au	VEGETATION ABOUND THE PHD APPEARS			\rightarrow // $-$
1604	OBSERVED A DRUM BUTTOM AT BASE OF SL			
1608	ZUD MOUNTORING WELL SHOWN ON THE	FIQURE	PICTURE, DIRECTION	
4	LY THE ROD WAS NOT FOUND.	200 4445 4 4 5 0	* DEALWAGE	1
- Ca 	(USACE) LA OBSERVED THE ABANDONEO	WELL :	FLOW DRECTION	
1624	LEFT SITE 10 : BULLED DRUMS		1/ SWAMPY AREA	
Scale:	1 square = PAGE 40		Scale: 1 square = PAGE L	HI Rite in the Rain

NE	CAPE	USACTE	THE CAP	E	USACE
SYE	AR REVIEW	9/4/13	5 YEAR	REVIEW	9/15/13
1625	ARRIVED AT SITE 15 09/14 11	FUEL TANKS	0730	PADERWORK & STREP	4 10 10 Z
	FOR A SITE WALK		0745	BREAKFAST	57 St (1 d)
1, 1, 1, 1, 2, 3,	45 YEAR REVIEW CHECKLIST ON A	4 SEPERME FORM	0800	BRISTOL TAILGATE	
1635	OBSERVED MONTORING WELL MI	<i>18</i> 8−3, €	0830	JACOBS TAILGATE	
	LOCKING HAS A LOCKING CH	P-WITH NO LOCK			
1	LATERUSH MOUNT MONUMENT A	DOES NOT CLOSE		PERSUNNEL	
)) V	AS THE WELL APPEACY TO			LACOBS J. ORCZEWS	CA SSHOTTECH
(4)	JACKED	•	-0	JACOBS C. FELL	SITELEND
		•			
1643	SITE HAS BEEN GRAPED/COM	UPACTED/AND		wx:	
	SEEDED TO PROMOTE POSITIVE			OVERCAST	
10	AND MUTICATE ERUSION.	•	= 6	LIGHT BREEZE	7
11				LOW 40sF	
(1) (4) (4)	LY OBSERVED THE REMEDIAL	CONTRACTOR (BRUSTON)			
10 10 15	SPREADING SEEP ON THE			POPE! LEVEL D MODIFIED	* 40
		•			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1645	LOCATIONS OF THE FORMER	ASTS GRE		DAILY OBJECTIVES	
#1 #X	NOT APPARAM			-SITEWALK PEMAINING =	7-SITES
10 10 10 40 46		5		- PREP FOR DEMOBIE	(4) (2) (2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4
1650	DEBRIS NOT OBSERVED ON	SITE OR AROUND			Mart Mart
	THE PERIMETER	Max			
		11/1/2			
1715	LEFT THE SITE LECTION	stepher D. Pell 9/14/13			$\begin{array}{cccccccccccccccccccccccccccccccccccc$
	square = PAGE 4		Scale: 1 squ	uare = PAGE 43	Rite in the Rain

NI CAPIE NE CAPE USAEVE 9/15/13 9/14/13 5 YEAR REVIEW 5 YEAR REVIEW SITE 293: DRHINAGE BASIN/ 0931 ARRIVED AT SITE 28: DRAIN AGE BASIN 195 YEAR REVIEW CHECKLIST ON A SUBITICITIES RIVER SEPERATE FORM & FLOW (0950 OBSERVED S 30 FT BY 60 FT SETTLING AUDS FOR 五四 COLECTING WATER & SEDIMENT FROM DREDGE OPERATIONS. 17 11 SPOINENT COLLECTION BAGS (2SFT X GFT X 12FT) nitis. JSED WENT PRESENT IN THE POUPS 11/ SWIMPY IREA Dan PHOPO, DIAMETRA IN GAL SYSTEM BY PRO ACT BEING USED TO TREAT SETTLING POND WATER PRIOR TO ONSITE DISPOSE (ONTO YON DRA) BASIN , 0956 WHERMEDIATE PUNDS ARE DEING USED TO LIFT WATER & SED LINEAT UPHILL WITH PUMPSTATIONS TO CARGO BEACH 10009 A SEDIMENT TRAP (STEEL WALL, 6FT WITH 3FT LINES) ROAD A SMALL DREDGE WAS BEING USED TO REMOVE SEDIMENT (ON PONTOONS) 1017 A JUIT MAIT SEDIMENT TRAP WAS AT THE MOUTH OF THE DRAINAGE, DID NOT OBSERVE SEPIMENT ESCAPING INTO THE SURITUGHNER RIVER VIO SITELL 1018 DID NOT OBSERVE DEPRIS IN THE DRAINAGE PAGE 45 Scale: 1 square = PAGE 44 Scale: 1 square =

NE CAPE	USARE	NE CAPE	USTE
S YEAR REVIEW	9/15/13	5 YEAR REVIEW	9/15/13
1027 LEFT SITE 28: DRAWAGE BASIN	•	SITE ZI:	WASTEWATER TAULC
		1// 1/2	****
1030 MET W/ ECO LAND SURVEYING AB	OUT SURVEY	STREW VI	9 xx 1, 1, x
OF SAMPLING LOCATIONS FROM 9/12/13	3	1/1/1/	
NEFD TO REMARK SITE 32		W 1/2/1/3	SILTERIA
DWILL VISIT SITE 7 & SITE 9 WIT	H THE	n.t.s 1"/	GRAVEC
SURVEYOR BEFORE LUNCH	•	1/0/	P40
1650 400 mg 4 6 4 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Autle	- VI /V	C B B C B C
1050 ARRIVED AT SITE 21: WASTEWATER TO			
7) THAN ZEVIEW FORM ON A DEPERATE	- Vask		
1105 OBSERVED BRISTOL (REMEDUL BONTRA)	ter SEFONG		
THE GRAVEL PAD AT THE END OF		069/15/13	A V
			HILL F
1109 GRAVEL PAD HAD BEEN AN OPEN EXCAULT	TION 3 DAYS		A.E.
AGO, NOW IS BACKFILLED WITH GRAVEL	WITH DY IS		
LITTLE SILT.			
LA SILT FENCE IS BETWEEN THE PA	D AND	CONCRETE	MANAGE BUTTALIS IN THE
OPEN WATER DOWN CRAPIENT		ESTEM) S	Marie 24 and 15
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Effective in the second
BACKFILL DOES NOT APPEAR TO HAVE		113	
COMPACTED AND IS TOO WET TO	00 80		ROND
(PUMPING UNDER FOOT)	•	BRNEL	
	1 1 -1		
Scale: 1 square = PAGE 46	2 7 1 1 1 1 1 1 1	Scale: 1 square =	PAGE 47 Rite in the Rain

NE	ECAPE	USACE	NE	CAPE		USACIE
S	YEAR REVIEW	9/15/13	54	EAR RE	VIEW PALLY & DOPE STORE	9/15/13
1121	LEPT SITE ZI: WASTELLATER TA	NK	7	SITI	E 16: HEAT & DUE PLA	गिर्मिडी
	PALINT & DOPE	STORAGE 6	7		INTERMEDIL	0 00 00 00 00 00 00 00 00 00 00 00 00 0
1123	ARRIVED AT SITE 18: HEAT & POWE	e PLANT CD9/15			TO SITE 28 CONTAINERS	6 0 86 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2.0 30 30	45 YEAR LEVIEW FORM ON AST				KADIMONES MM	
1125	MET WITH SURVEYORS TO SH	fow WITERE	N		Mourtague L	
1155	SAMPLING LOCATIONS ARE		n.t.s.	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PILE	
	1 1 2000		+ 0			XXXX
	LEFT SITE FOR LUNCH			6 6 7 6 7 6 7	AMADONEO !	ABANDON ED
1230	LEFT CAMP FOR SITE				OB THE TELLED TO	X X X
1241	ARRIVED ON SITE 16 PAINT	THE PLANT		140,00	O G GLADEO	
1251	OBSELVED AN ABANDONEP MONIS	URING WELL	=0			
	THAT WAS NEAR THE SW COR			GRAV	EL ROAP	
	FORMER BUILDING					
						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1257	OBSEQUED AN ABANDOMED MONITORIN	16 WELL THAT		C	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	WAS NEAR THE NW CORNER OF	THE SITE.		- APPROX S	SITE BOUNDARY	1
	LISURFACE WAS FILED WITH NAT	TUE MATERIAL	10		UNITORING WELL	
	SOME OF THE CONCRETE FROM	THESULFACE		DISTURBED G	ROUND GRADED AREA	
10	Confieron			E E E	C C 2	
				TAKEN AP	TER PICTURE II AT MO	C SITE (PG 51)
1300	SITE HAS BREN RECENTLY GLADED	AND SEEDRD				
F	ON THE SE BRTICW			F X 3		
Scale:	1 square = PAGE 48		Scale: 1	square =	PAGE 49	Rite in the Rain.



NECHE	USLEE	NE CAPE	USACE
5 YEAR REVIEW	9/15/13	5 YEAR REVIEW	9/15/13
1350 BUILDING AT SITTE 13 HAS I	STERN REMOVED	1415 5 YEAR REVIEW PAPE	FLUORIS
ALONG WITH THE POUNDATION	N	to and QC	
		1800	
353 BUILDING & FOUNDATION ON THE	NUE PORTION OF		6
SITE 19 HAS BEEN REMOVED.	THE FOUNDATION		F
FOR THE BUILDING ON THE SI	VADRTION OF		
SITE 19 REMINS,	* 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	End of Do	2)
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	<u>P</u>	The state of the s	
355 SITES 13,15, \$27 HAVE BEEN		TWO	25 9 9 1 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
GRADED, AND SEEDED TO PRUM			
DRAWAGE AND MITIGATE E			(C) (A) (A) (A) (D) (D) (A) (A) (A) (C) (A) (A) (A) (A) (A) (A) (A) (A) (A) (A
THE NORTHERH MALF OF SI	7E19		
6	2 1 2 1 1 1		
1356, MONITORING WELLS IN THE C			
OF THE MAW OPERATIONS COMPI	LEX (NOC) WELL		
NOT OBSEVED	0 00 05400 50		No.
DURING EXCAUNTION	D CR KIEMOLOGO		
DOIGN & EXCAUATION	7 1 1 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	9/1	5/12
4000 LEFT SITE	4 9 0 6 6 6 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
415 BACK AT CAMP	1 1 0 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
# # F # F # F # F # F # F # F # F # F #	1 0 6 7 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Service of the servic
Scale: 1 square =PAGE	57	Scale: 1 square = PAG	E 53 Rite in the K

USACE	NECAPE	USACE
	5 YEAR REVIEW	9/16/2013
	= 1030 - PREP GEAR +	or Demob
WSKA	1415 - FLIGHT TO 1	00 9/16/13
0 A A B B A		/ 1 (DA 1) = D (1 E 1 2 E)
40 +	1300 - INTERVIEW W	J. CANNOLK (COALE)
no	36 FT 76 6	EDINE FATO DODG
•	CARL MALE	LENT LOND IN THIS
	00411480	IS LOW AND
2		ren WOULD LIKELY
		RISIC OF SPREADING
OAR for		ATRI SEDIMENT
uning		
ns	SITES W/ MA	DA REMEDIES
	-PLAN TO	EPAIR WELLS DEXT
ulgate		Richard Stoler
	- PLAN TO	AVGUENT NETWORK
e	TOPPOULD	E SUPFICIENT NOWITORING
N 1 4 7 N	NEXTYEAR	DESTAILEY : 1
paperwort	1412	
	2000-DEMOBE TO AND	Albancation
	2130 - END OF 15 (12
	1 11000	D. Fell 9/613
z 54	Scale: 1 square =	PAGE 55 Rite in the Rain.
	e for e for erwork QAR for unong ins	EVERY REVIEW 1030 - PREP GEAR TO DE 1300 - TINTERVIEW WITH 1415 - PENGLE WITH 1415 - PENGLE TO LOWER 1415 - PENGLE TO LOW

NE	CAPE		USACE
5	pear RE	VIEW	PHOTOLOG
	* * CO	MINI	LED FROM PG61X
Date	Photo#	Div.	Description
9/14/13	070	NA	Site 29 Drum in Pond
	Ø71	SE	Site 29 Sugi River
	072	NW	Site 29 Sugi River
	073	8W	Site 8 South overrew
	074	NE	Site 8 North Overview
	075	W	Site 10 Debris
	076	NIA	Site 10 Monutoring well
-/-	077	S	Site D Busto Stague
/:	078	N	Site 10 Bristol Staging
1 1	079	NIA	Site 10 Concrete Ring
	080	NA	Sitel drum lid
	Ø81	NIA	Site 10 abandonedwell
	082	NW	Sitell overview
	083	8W	Sitell overview
/:	084	NA	Sitell monitoring well
9/14/13	085	N	Sitell seeding
9/15/13	086	N	Site 28 Sedim Pond
	Ø87	W	Site 28 Water filters
	088	NW	Site 28 Sediment Tubes
	089	E	Site 28 Intermed Rand
	090	N	Site 28 Floculate add
/	091	N	Site 28 Intermed Pond
9/5/13	092	NE	Siteal Oleview.
Scale: 1	square =		PAGE 56

NE CAPE 5 YEARREVIEW

USACE Photo LOG

	7 - 7	-	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Date	Prioto#	Dir	Description
9/15/13	093	Sow	Site 28 Overview
	094	E	Ste28 Water Rump
/	095		Site 28 Sedument Prap
	096	N	Site 28 Bristo Demob
	097	S	Site 38 averiew
1		S	Site 28 Dredge
	099	E	Site 28 Drainage to Sugi
	100	E	Site 28 Wattles before Sug
/	101	W	Siteal Road
/	102	W	Site al Road
	103	SE	Site 21 Backfill
	104	E	Site 21 Backfill
	105	W	Siteal Silt Fence
	106	S	SiteRI Seeding
	107	E	
	108	N	Site 21 Road 528 Sitelly Overview Acces
	109	NA	Sitely Abandoned well
	110	E	Sitella Overview
	(11)	S	Sitelle Overview
	112		Sitelle abandoned wel
/-	113	N	Site 16 Abandoneolur 1
	114	N	MOCOVERVIEW
7/15/13	115	N	moc Duelview

Scale: 1 square = PAGE S7 Rite in the Rain.

5 year Review	USACE		NEC	CAPIE		USHETE
NE CAPE	PHOTOLOG		S-YR	REVIEW		PHOTO LOG
Date Photo# Dir. Desc	ription	D/	ATE	PHOTO #	DIRECTION FACING	DESCRIPTION
	Monitoring well	9	12/13	001	5	CALIBRATION YSI
	GeoTek	91	12/13	002	S	SITE KMS SAUPLING
(118 W MOC	Overview	91	lizlis	003	N	SITEONERVIEW
119 WNOTE			1	004	N	7LF GW SAMPLING LOCATION
) 120 N Site 13	menien	9	12/13	005	NIE	9LF GW SANPLING
/ 121 8E Sitel	5 Overview		Mizli	006	nla	9LF GW TURBIDITY
(122 N Site 2	Fdrainage	9/	13/13	007	N	Gwattempts 7LF00112112
123, N Sites	27 Welldebris	9	113	008	N	Site 32 Reading depression
	Overview		1/13	009	WE	Site 32 Readway depression
9/15/13 1 25 S MOC	Overview		4/13	010	# SW	Site 30 Diaper transmody
	6 A 20 C 2 3 3 C C C C 2 C 2 2		4/13	0111	d WS	Site 32 Debrus Old foundate
			1/13	012	W	Site32 Debris
		9	1/13	013	NA	Site 32 Asphaltic debris
		0	1/13	014	N	Site 32 culvert
	4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	C C	1/13	015	E	Site 32 culveret
	10		1/13	016	S	Site 32 metal debris
		C	1/13	017	W	Site 3) Recent grading
			9/13	018	N	Site 31 Antenna foundation
			1/13	019	W	Site 31 Antenna foundation
			1/13	020	E	Site31 Metal debris
		9	1/13	021	NA	Site31 Drain
1 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	9 0 0 0 T 7.5 0 0 0 0 8 2 0 0 0 0 0 0 0 0		9/13	002	N	Site 31 Drainage
	$\begin{pmatrix} 1 & 1 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 \\ 0 & 0 &$	9	13/13	023	N.	Site31 Depression
Scale: 1 square = PAG	E 58	Sc	ale: 1 s	quare =	E- 3-)	PAGE 59 Rite in the Rain.

NE CAPIE PHOTO LOG 5-YR REVIEW DIRECTION PHOTO # FREING DESCRIPTION Site 31 Foundations AE 9/13/13 924 Site 7 Debris 025 N Site 7 Metal Debiis NA 026 N/A Site 7 Hetal Debris 027 028 Site I Rusted Drums 029 Site 7 debris in Ronds Bite 7 landfill cap 930 W Site 7 Debris in Rond 031 NW Site7 Debris in Pond 033 Site 7 Debris in Pond W 034 Site 7 landful cap Site7 topofcap 0.35 Site 7 Armored each 036 0 37 NA Site 7 Debnis 038 Sitc7 Debris Site 7 Abandoned well loc. NA Site 7 Debris in Pond 040 NA Site 7 Possible Deun 0 42 N/A Site 9 Abandoned well a Site 9 Diversion trench W Site 9 landfill cap W Site9 Vegetation Site9 Pond near cap Scale: 1 square = PAGE 60

USACIE

(=)

C=4

NE CAPE USACTE PHOTO LOG 5-4R REVIEW DIRECTION FRENCE DESCRIPTION PHOTO # Site9 Culvert 9/3/3 047 9/14/13 0 4 8 Site 1 Pond 049 Site Cracking edge Site lading equip 050 Sitel Runway NE Site 4-wheel trail offermaly 052 NE Site 3 Overview 053 W Q54 SW Site3 Pond on site 055 S Site3 Pond onsite Site 3 Recent excavation 056SE Ø57 NA Site3 Sheen in Pond Ø 58 NA Site le Abandoned well 059 NA Site WAhandoved well \$60 E Site 10 Bristo Staguna Q 6 1 NW Sitely BRISTO Stagular Site 6 Nearby Pond QUQ E Site 29 Overview of Road 0103 064 Site 29 Over trew from Road M \$65 Site 29 Sugi RIVER Site 29 By is 161 Water Intako 0668F Site 29 Sugi River 067 E Site 29 auguent 068 9/4/13 069 W Site 29 Sugi RWEN -X CONTINUED ON PAGE 56 X Scale: 1 square = PAGE 61 Rite in the Rain

NE CAPE USACE SYR REVIEW ETRACKING CONTAINER TYPE / DESCRIPTION SEN DATE COUTENTS COUTAINER ID 9/12/13 HECON/PURGE Sigallan backet BNECAPE-B1 NON-HAZ SHIPPED TO NOME 9/13/13 S-gallen bucket NOW - HAZ IAN/APIE 9/12/13 13NECAPE-BZ HADDED TO BRISTOL'S Scale: 1 square =



Outdoor writing products . for Outdoor writing people



Copier & Ink-Jet Paper



Bound Books



Loose Leaf with Ring Binder



Memo Books



All-Weather Pens



Notebooks

RiteintheRain.com

APPENDIX D Photograph Log

PHOTOGRAPH LOG TABLE OF CONTENTS

Photo Number	<u>er</u>	<u>Page</u>
Photo No. 1	7 August 2013 Cargo Beach Road and Site 7 Landfill. View facing southwest.	D-1
Photo No. 2	7 August 2013 Site 7 Landfill East. View facing northwest	D-1
Photo No. 3	7 August 2013 Site 7 Landfill North Corner. View facing southeast	D-2
Photo No. 4	7 August 2013 Site 7 Landfill Southeast corner. View facing southwest.	D-2
Photo No. 5	12 September 2013 Overview of Northeast Cape Site. View facing north.	D-3
Photo No. 6	14 September 2013 View of a pond adjacent to Site 1. View facing south	D-3
Photo No. 7	13 September 2013 Wood debris at Site 7. View facing north	D-4
Photo No. 8	13 September 2013 Metal debris at Site 7.	D-4
Photo No. 9	13 September 2013 Metal debris at Site 7.	D-5
Photo No. 10	13 September 2013 Drum debris located near a pond at Site 7. View facing north.	D-5
Photo No. 11	13 September 2013 Debris in pond located adjacent to landfill cap at Site 7. View facing north.	D-6
Photo No. 12	13 September 2013 Condition of northern edge of landfill cap at Site 7. View facing west.	D-6
Photo No. 13	13 September 2013 Miscellaneous debris in pond adjacent to landfill cap at Site 7. View facing north.	D-7
Photo No. 14	13 September 2013 Miscellaneous debris in pond near landfill cap at Site 7. View facing northwest	D-7
Photo No. 15	13 September 2013 Metal debris in pond adjacent to landfill cap at Site 7. View facing north	D-8
Photo No. 16	13 September 2013 Condition of northern edge of landfill cap at Site 7. View facing west.	D-8
Photo No. 17	13 September 2013 View standing on top of landfill cap at Site 7. View facing northwest	D-9
Photo No. 18	13 September 2013 Condition of armored rock on the southern border of landfill cap at Site 7. View facing east	D-9
Photo No. 19	13 September 2013 Debris protruding through the southern side of landfill cap at Site 7.	D-10
Photo No. 20	13 September 2013 Debris located with the armored rock at Site 7. View facing south.	D-10

PHOTOGRAPH LOG TABLE OF CONTENTS

Photo Numbe	<u>r</u>	Page
Photo No. 21	13 September 2013 Abandoned monitoring well filled with bentonite at Site 7.	D-11
Photo No. 22	13 September 2013 Debris in pond south of landfill cap at Site 7. View facing south.	D-11
Photo No. 23	13 September 2013 Apparent drum located in pond south of landfill cap at Site 7	D-12



 $\begin{tabular}{ll} Photo No. \ 1-7 \ August \ 2013 \\ Cargo Beach Road \ and \ Site \ 7 \ Landfill. \ View facing \ southwest. \end{tabular}$



Photo No. 2 – 7 August 2013 Site 7 Landfill East. View facing northwest.



Photo No. 3 – 7 August 2013 Site 7 Landfill North Corner. View facing southeast.



Photo No. 4 – 7 August 2013 Site 7 Landfill Southeast corner. View facing southwest.



Photo No. 5 – 12 September 2013 Overview of Northeast Cape Site. View facing north.



Photo No. 6 – 14 September 2013 View of a pond adjacent to Site 1. View facing south.



Photo No. 7 – 13 September 2013 Wood debris at Site 7. View facing north.



Photo No. 8 – 13 September 2013 Metal debris at Site 7.



Photo No. 9 – 13 September 2013 Metal debris at Site 7.



Photo No. 10-13 September 2013 Drum debris located near a pond at Site 7. View facing north.



Photo No. 11-13 September 2013 Debris in pond located adjacent to landfill cap at Site 7. View facing north.



Photo No. 12-13 September 2013 Condition of northern edge of landfill cap at Site 7. View facing west.



 $Photo\ No.\ 13-13\ September\ 2013$ Miscellaneous debris in pond adjacent to landfill cap at Site 7. View facing north.



Photo No. 14-13 September 2013 Miscellaneous debris in pond near landfill cap at Site 7. View facing northwest.



 $Photo\ No.\ 15-13\ September\ 2013$ Metal debris in pond adjacent to landfill cap at Site 7. View facing north.



Photo No. 16-13 September 2013 Condition of northern edge of landfill cap at Site 7. View facing west.



 $\begin{array}{c} Photo\ No.\ 17-13\ September\ 2013 \\ View\ standing\ on\ top\ of\ landfill\ cap\ at\ Site\ 7.\ View\ facing\ northwest. \end{array}$



 $Photo\ No.\ 18-13\ September\ 2013$ Condition of armored rock on the southern border of landfill cap at Site 7. View facing east.



Photo No. 19-13 September 2013 Debris protruding through the southern side of landfill cap at Site 7.



Photo No. 20-13 September 2013 Debris located with the armored rock at Site 7. View facing south.



 $\begin{array}{c} Photo\ No.\ 21-13\ September\ 2013 \\ Abandoned\ monitoring\ well\ filled\ with\ bentonite\ at\ Site\ 7. \end{array}$



Photo No. 22-13 September 2013 Debris in pond south of landfill cap at Site 7. View facing south.



 $\begin{array}{c} Photo\ No.\ 23-13\ September\ 2013 \\ Apparent\ drum\ located\ in\ pond\ south\ of\ landfill\ cap\ at\ Site\ 7. \end{array}$

APPENDIX E Completed Interview Questionnaire Forms

Interview Record

Name: Robert	Annogiyuk	Date:	15-2014
Organization:		Phone Number:	
Title:		Email:	
Interview Type:	Mail/Email		Phone/In Person
Site (s) Name:	Northeast Cape, St. Lawrence Island		

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

3. Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details.

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

Not well informed Because of some of the Technical Terms.

Contaminants + what they mean.

- more Introductory information would be helpful so people con get a better perspective.

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?
7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?
in the past five years that you reer may impact the protectiveness of the site?
8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

Interview Record

Name: Orville toolie		Date: 1-15-14		
Organization:		Phone Number:		
Title: Commonity Member		Email:		
Interview Type:	Mail/Email		Phone/In Person	
Site (s) Name:	Northeast Cape, St. Lawrence Island			

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

doing pretty good - a lot cleaner than
Savaonge

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

3. Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details.

No -

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

People of Savoonga know whats going on.

- Hetters from the corps to upolate
the community

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?

7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?

use the area for local housing

8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

- Would like to have more Evolution of unstands token off the site tused as Boilding Materials Name: Kukulget Inc.

Board of Directors.

Organization:

Title:

Interview Type:

Mail/Email

Northeast Cape, St. Lawrence Island

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

* Cleanup is a good thing

* How much of that backfilled gravel is contaminated or over contaminated soil:

1952 agreement to Native Village of Saavoonga to return site to original condition.

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

* Concerns about what contaminants were left there near the camp.

* meathe camp.

* military lise - left overs were dumped and community princing members pecked through the dump to get to the and

Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details. * Reports that Bristol + employees were taking your wheelers and beach combing which irolated the agreement with the landowners. (Every summer sine work has been performed) * Hedwar injured personell while chanup going on (2012 and 2013) 4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site? - Don't get too technical - put it in laymens terms. - more information about how what areas are clean and which areid. * Decision Document wasn't explained or Major presented to the community. Continue contere 5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site? * Site walk to previous areas. to get updates. Tribal Council or Corporation would * Add signage to the landfills laxound at least the perimeter to notify site visitors. nave a copy * Add monitoring wells to Panolfills of the Signed to avoid hitting them in the winter. document

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document? — Cap was seeded with "local grass" — Cap was seeded with "local grass" — Cap was can't grow on kocks" & Open up cap mater Cap take out debris and change cap mater add soil.
7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site? **A Don't drink water from NE Cape anymore **A No longer use Kangukhsam Htm Spering.
8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?
management or operation? * Left 2 landfills; if you are already taking * Left 2 landfills; if you are already taking out all of that soil; why not remove the debris. * Site 7; engine, airplane, transformers; batteries, road grader, barrel all seen beneath the sueface, Cleanup was only at the surface.
(moc. all will dor's left in place 1999-20th; more utilarlors left in place mor. one at Rol 98, loading feame was located. Septie tank between Site 21 and Site 28. To Followup; with information to community or Remedial Efforts.

+ Another dump a South of Radome Site is Site 100ated (Site 33?) "Clean it up" Community members observed helicopter activity abound to the south side of the mountain. Believed to * Commercial fishing hot spot outside of Sniger River Drawage. Close to Panol. * West side of mte Kangukksam Mtn.
10+ drums seen while hunting * Studge at Site 24 below ponds Barrels still remain. * Long-term moratoring of the Sugi River
The lagoon at the stab end of Sugi
freezes up. When it opens water
movement increases * Corps should maintain the aurstrip * POL sites limited to Oft below ground water. Not getting to clean. Contaminations * Fragments of as bestos + concrete slabs left at Site 31 + MOC. would like them Removed. >> what is underneath them what if we disturb. Them to use the land?

Name: Dena T	Kolowiyi	Date: 1 - 15 - 2014
Organization:		Phone Number:
Commonity	MemBei	
Title:		Email:
Interview Type:	Mail/Email	Phone/In Person
Site (s) Name:	Northeast Cape, St.	Lawrence Island

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

Cless-up part is going ok. Happy work is moving Forward

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?

7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?

8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

When can you get information. Why are taling so long? Feels like some community, concers are not Being addressed.

(Health)

Formily memsus were put at Risk by participating in clear-up prior to Hazwaper-

Name:	theld.	Date: 1-15-2014	SHIME
Organization: Common ity		Phone Number:	
Title:		Email:	
Interview Type:	Mail/Email	il Phone/In Person	
Site (s) Name:	Northeast Cape, St.	. Lawrence Island	

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

Email maps of what Areus are above the Classiff level-

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

· Beachcombers are concern, Becombe in my opiosion I consider it transpossing.

3. Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details.

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

Likes the forms of the bos meetings good in Franchisa.

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?

7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?

8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

Would like to move out the future

Name: Name With	rheld	Date: 01/15/2014
Organization:		Phone Number:
Title:		Email:
Interview Type:	Mail/Email	Phone/In Person
Site (s) Name:	Northeast Cape, St.	Lawrence Island

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

want the whole wea cleaned up - not

just the individual site. lack of information /

understanding

concern about ammo, weapon storage

at NE cape - where location in it contamination

Remain.

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

Callons of heating fuel-Health problems in Savoongaproblems that didn't exist before NO

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

No- would like more information about what they have found

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

NO

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?

No good understanding of the DD and how it was signed etc.

Now it was signed etc.

* SW Cape, Sipenpak Camps,

- material used contain lead-based pount that

originated at NE cape. Built and tax used.

7. Are you aware of any changes in land you care.

7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?

NO

8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

To not have confidence that the land's clean.

"I don't want to use that land!" It might still be durty."

Name: Pamela Miller and Vi Waghiyi	Date: 1-24-14
Organization: Alaska Community Action on Toxics and Native Village of Savoonga Tribal Member (Vi)	Phone Number: (907) 222-7714
Title: Executive Director (Pamela Miller) and Environmental Health and Justice Program Director and NVS Tribal Member (Vi Waghiyi)	Email: pamela@akaction.org and vi@akaction.org
Interview Type: Mail/Email	
Site (s) Name:	Northeast Cape, St. Lawrence Island

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

The clean-up of the Northeast Cape site is far from complete and not protective of the health of the people living on the Island. We believe that the site was not properly characterized and thus the remediation has not been fully informed enough to identify and remove important source areas of contamination. Source areas of contamination are still contaminating the Suqi River and ground water. We are concerned about continuing contamination of the Suqi River and estuary from fuel-related compounds from prior large spills, PCBs, and pesticides. The Suqi River, once a prime fishing location for the people of St. Lawrence Island, has not recovered because of the damage caused by the military occupation, activities, and on-going contamination from sources areas.

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

The original community at NE Cape, the Native Village of Northeast Cape, was and continues to be displaced by the military operations at NE Cape. The people of St. Lawrence Island intend to re-establish the community at NE Cape, however cannot do so until they are assured that the cleanup is protective of health and well-being for a residential community and future generations. People cannot safely use the NE Cape area for traditional hunting and fishing or for the harvesting of food (greens and berries) and medicinal plants. The ground- and surface sources of drinking water sources are not safe.

Monitored Natural Attenuation is not an acceptable remedy as it will take decades for levels of contamination to reach "safe" levels. The contamination has already harmed the health of generations of families associated with NE Cape. Overall, we do not think the remedies are protective of health and the environment. We think and the tribe supports that other active remediation methods must be used, including additional and effective removal as well as active chemical oxidation as proposed by the RAB Technical Advisor.

Cleanup standards are far from adequate. For example, DRO cleanup standards for soil are 9,200 mg/kg. At those levels, contaminated soils will continue to serve as a source of contamination to ground- and surface waters. We believe that the contamination remaining in landfill sites at NE Cape is of great concern for health since they were simply capped and will remain in place and unabated. Leachate from these landfills will continue to harm and present hazards to the Suqi River watershed, fish and wildlife, and people's health.

Detection limits used for analysis and Aroclor analysis rather PCB congener analysis are not adequate methods to properly characterize the nature and extent of contamination. The analytical methods are not sensitive enough to assess the range of contaminants known to exist in the sediments, soils, water at NE Cape. Analyses should include: congener-specific PCBs, mirex, HCB, dioxins/furans, DDE, BTEX, PAHs, and others. Also, we think that TCE and other solvents, as well as vinyl chloride should be included among the analytes. People are also concerned that there might be undisclosed information about what harmful substances were used and/or left at NEC, including the possible use of radionuclides/radiation hazards.

The Army Corps of Engineers has not conducted proper government-government consultation according to their legal obligations. The past Corps of Engineer's Project Managers have not been culturally sensitive.

3. Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details.

The military was not been responsible for posting proper signage in the Yupik language to warn people about the hazards of the site following their abandonment of the site. Therefore, people salvaged hazardous materials and used them for homes and cabins. Also, to this day, there are no warnings concerning the danger of consuming water from the Suqi River.

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

We had to submit a petition to the Army Corps of Engineers to establish a Restoration Advisory Board (RAB). Although the RAB meetings provide information sharing, concerns and information requests expressed by community members and our technical advisor have not been respected or acted upon.

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

The site cleanup should not be closed at this stage because of the remaining contamination. Long-term monitoring should include re-installment at sites where monitoring wells have been removed and installment of new monitoring wells in key locations such as down gradient from

the Main Complex and the landfill sites (including sites 7, 9, 10, for example). Integrative sampling methods should be employed within the Suqi River (such as SPMDs), as well as sediments cores within the Suqi River and its estuary, biological sampling of fish and wildlife that use the NEC area. As mentioned above, proper analytical techniques and improved characterization must be done. As stated by the RAB technical advisor, the estuary needs improved characterization and should be subjected to innovative remedial measures to reduce the concentration and distribution of chlorinated (PCBs, mirex, DDE and others), non-chlorinated organics, and metals (e.g. Hg). The Corps of Engineers has disregarded the on-going contamination by PCBs in the Suqi River and effects to water quality of the soluble PCB congeners and input to the estuary.

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?

Yes. The tribe should be an official signatory to the Decision Document. The site should continue to receive active remediation and not be closed – additional monitoring and remediation is needed as discussed above.

7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?

As described above, the remedial actions have not been sufficient to protect the health of people of St. Lawrence Island. Physical processes used to remove contaminated sediments are likely or will likely uncover additional contaminated sediments. This is not acceptable since previous sampling may not have included elevated concentrations. Disturbed samples are a new environment and may result in further exposures.

The cleanup is NOT complete and unless it is completed, it will continue to cause harmful exposures and prevent adequate health protections.

8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

The RAB community members, tribal leaders, and RAB technical advisor's knowledge, concerns, and recommendations have not been followed or addressed by the Corps of Engineers or their contractors. Jacobs Engineering, as the third party independent reviewer, should review past RAB meeting minutes, RAB member statements/comments, and Technical Advisor statements and include these in the Review since most of these expressed concerns have not been addressed. These concerns and recommendations must be addressed for the protection of the health and well-being of the St. Lawrence Island Yupik people and future generations.

I	NTERVIE	W RECORI	D
Site Name: Northeast Cape			FUDS ID No.: F10AK096903
Site Location: Northeast Cape, Sain	t Lawrence Island,	Alaska	
Subject: First 5-Year Review			Date: January 27, 2014
Interview Type: ☐ Telephone ☐ Visit ☐ Email ☒ Questionnaire		🛚 Questionnaire	
	Interv	iewee:	
Name: Curtis Dunkin	Title: Environme Specialist	ntal Program	Organization: Alaska Department of Environmental Conservation
Telephone No: 907.269.3053 Fax No: 907.269.7649 E-Mail Address: Curtis.dunkin@ala	ska.gov	Street Address: 5 City, State, Zip: A	555 Cordova St. Anchorage, AK 99501

The following general questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

INTERVIEW QUESTIONS

1. What is your overall impression of the project?

Remedial activities at Northeast Cape (NEC) have been ongoing for over 15 years; of which mobilizations to conduct remedial actions and remedy implementations have been occurring at the site the past 5 consecutive field seasons. In the past six years the Army Corps of Engineers (Corps) has prioritized the resources necessary to implement the cleanup at NEC and it is ADEC's understanding that the Corps plans to continue doing so until all remedies are implemented and protectiveness is achieved at all NEC sites. Remedial actions at NEC have been a very large and complicated undertaking due to the remoteness of the site, the short field season, and the complexity of the contamination issues. Overall, ADEC perceives the remedial activities to have occurred in an adequate and timely manner that is in accordance and consistency with CERCLA law and ADEC regulations. To date, a large majority of the planned removal actions have been completed and it is ADEC's understanding that the Corps plans to continue mobilizing and conducting remedial actions in the 2014 field season as well as in future years to continue cleaning up and/or monitoring the contamination at the NEC sites.

ADEC will be submitting comments pertaining to each specific site being evaluated as part of this First Five-year Review for NEC to be considered and included in the draft 2014 Five-year Review Report after ADEC has received and reviewed the draft 2013 NEC Remedial Action Report.

2. From your perspective, what effects have site operation had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision Documents?

Saint Lawrence Island residents and community members have expressed both gratitude that the NEC FUDS is being cleaned up as well as concerns regarding the overall protectiveness of the remedies in the 2009 Decision Documents. From ADEC's perspective, the immediate effects of site operations on the surrounding community (Savoonga and the Native Village of NEC) have been positive mainly due to the decrease in human and environmental exposure risks via the removal and offsite disposal of extensive volumes of contaminated soil. ADEC will be submitting comments pertaining to each specific site being evaluated as part of this First Five-year Review for NEC to be considered and included in the draft 2014 Five-year Review Report after ADEC has received and reviewed the draft 2013 NEC Remedial Action Report.

3. Are you aware of events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details.

ADEC is not aware of any events of vandalism, trespassing, or emergency responses from local authorities that have occurred in association with the NEC FUDS and/or its associated contamination issues.

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

ADEC staff travel to Savoonga twice a year to attend the semi-annual Restoration Advisory Board meetings. ADEC staff travel to NEC at least once annually to conduct multi-day facility-wide site inspections of the remedial activities being conducted during the field season; and has in recent years conducted two separate site inspections. ADEC staff regularly participate in in-person meetings and teleconferences with project team members as needed. ADEC staff, per ADEC's CERCLA regulatory authority, review, submit comments, and grant approvals of work conducted in association with the contaminated sites issues at NEC. During field seasons when remedial activities are being conducted at NEC, the Corps has kept ADEC apprised with daily quality control and progress reports. The Corps has also notified ADEC in a timely manner whenever there has been a change in site conditions and/or when it has required ADEC's review, input, and approval to implement remedial activities.

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

Yes. ADEC will be submitting comments pertaining to each specific site being evaluated as part of this First Five-year Review for NEC to be considered and included in the draft 2014 Five-year Review Report after ADEC has received and reviewed the draft 2013 NEC Remedial Action Report.

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?

ADEC is not aware of any problems which have required or will require changes to any of the selected remedies or the two 2009 Decision Documents. ADEC will be submitting comments pertaining to each specific site being evaluated as part of this First Five-year Review for NEC to be considered and included in the draft 2014 Five-year Review Report after ADEC has received and reviewed the draft 2013 NEC Remedial Action Report.

7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?

ADEC is not aware of any changes in land use, access, or site conditions associated with NEC which have occurred in the past five years that have had or may have an impact on protectiveness. ADEC will be submitting comments pertaining to each specific site being evaluated as part of this First Five-year Review for NEC to be considered and included in the draft 2014 Five-year Review Report after ADEC has received and reviewed the draft 2013 NEC Remedial Action Report.

8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

ADEC will be submitting comments pertaining to each specific site being evaluated as part of this First Five-year Review for NEC to be considered and included in the draft 2014 Five-year Review Report after ADEC has received and reviewed the draft 2013 NEC Remedial Action Report.

9. Miscellaneous Comments:

ADEC will be submitting comments pertaining to each specific site being evaluated as part of this First Five-year Review for NEC to be considered and included in the draft 2014 Five-year Review Report after ADEC has received and reviewed the draft 2013 NEC Remedial Action Report.

Name: Mitchell K	inuk look	Date: 4Feb 2014
Organization: Pres. of Native	Vellage of	Phone Number:
Title:	Savoongo	Email:
Interview Type:	Mail/Email	Phone In Person
Site (s) Name:	Northeast Cape, St.	Lawrence Island

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions

1. What is your overall impression of the project (general sentiment)?

- looks like to be more cleaned up

Buried drums - at the landfills—would like them cleaned up.

- Recycling Metals place - found trace of radiation—

- Recycling Metals place - found trace of radiation—

- Out call ?

29 Jan 14?

- PAT

- FOR

- Ron Scudato

- Ro

2. From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, - increase incidence of cancer - concerned with the high rate of cancer on the island.

- thigh rate of PCB in the blood. administration, implementation, or overall protectiveness of the remedies in the Decision

3. Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing,
or emergency responses from local authorities? If so, please provide details.
, Collection of construction materials for use around the state
or emergency responses from local authorities? If so, please provide details. Collection of construction materials for use around the island. Historic
Historic a lot of exposure occurred during this time.
a lotat avoisure occurred and
and approximately

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

-> Help to underestand what cleanup levels mean.

-> Better explaination of what the regulations

mean and how the cleanup levels

were established. Not really -

5. Do you have any suggestions regarding future operation, maintenance, and monitoring

Cleanup should be longer.

Cleanup should be longer.

DRO-spill at Site 11 -> could smell the DRO approx 6-7 miles. - DRO level is too high.

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document? Possible vadiation that was identified— Trace identified—
- Possible vadiation that was mentioned - on vecycled metals. (Trace identified - unclear on location or source) unclear on location or source) — want it removed from the land.
- want it removed from the land.

7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site?

Sugi river basedoes not have as much fish as before

seal numbers have gone done - slowly returning

Subsistence is affected. The area is not used.

Subsistence is affected. Slowly returning.

8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

Do more research and testing of the soil + water.

- Provide information be five the reports come

- Provide Valage of Sawongo

rut. Native Valage of Sawongo

Sampline of the reinology again initiated.

- now that cleanup efforts have been initiated.

- dust shrup, waching, etc.

- dust shrup, waching, etc.

Name: Paul Ro	okok	Pate: Of Feb2014
		hone Number: \mathcal{U}/\mathcal{A}
Title:	J	Email:
Interview Type:	Mail/Email	Phone/In Person
Site (s) Name:	Northeast Cape, St. La	wrence Island

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.

Interview Questions 1.) What is your overall impression of the project (general sentiment)? A Cleanup missed in areas that weren't included as a 87HS — As a laborer we were told to only cleanup the areas that were within the 81te. Wires and cables remain and were mostly covered by vegetation & water. "overall it's a fair yob - not a good one." 3 Amore Sampling should have been done cluring 3 the RIS to get a better sense of whats there. -Took a lot of talking to get and old truck venoue from laidfill east From your perspective, what effects have site operations had on the surrounding community? Are you aware of any community concerns/complaints regarding site operations, administration, implementation, or overall protectiveness of the remedies in the Decision only a handful of people know about the cleany.

most share holders don't have any ideas.

toget information out- more retails are

meded to be explained - UST buyman's terms.

To the corporation

B

3. Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details.

Shareholders in Lambell complaining about vecreational activities in their lessure trane—comployees that were not shareholders well kiding. At offsite that were not shareholders were taking artifacts, and rumans indicate they were taking artifacts, and rumans indicate they were taking artifacts, and rumans indicate they are cultural and tadchonal wahre loop. These are cultural and tadchonal terms.

4. Do you feel well informed about the site's activities and progress? Have there been communications or activities regarding the site?

We need something float explains what seen chand up that everyone can understand.

The only a handful of people know- just people that worked there

People that worked there it doesn't doing and why tell a complete story. What they are doing and why tell a complete story. What they are doing and why

5. Do you have any suggestions regarding future operation, maintenance, and monitoring (OMM) at the site?

Work with Native Corp at Sawoong at Gambell and The IRA.

project the artifacts t respectency comments

6. Have any problems been encountered which required, or will require, changes to the remedy or Decision Document?

abetler understanding. of DD.

7. Are you aware of any changes in land use, access, or other site conditions that have occurred

in the past five years that you feel may impact the protectiveness of the site?

Site be long to Gambell & Savonep.


8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?

Should be up to the Corporations of not any body.



Name: Deltoest	Pungowini Date: ONFEBROW
Organization:	Phone Number:
Title: Former Rees of Na	1. Village of Savoon a Email:
Interview Type:	Mail/Email/ Phone/In Person
Site (s) Name:	Northeast Cape, St. Lawrence Island

The following interview questions are based on EPA guidance (EPA 540-R-01-007). Questions may be left unanswered if they do not apply to you.



3. Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details. 110. - Difficulty to deal w/ Comps Don't want to deal of corps of the - should be dealine with washington. Government -to-Government relation ships are non-existence. There No need to deal with Alaska: This is is a federal issue. - Repatriation Act of Aleuts. 5. Do you have any suggestions regarding future operation, maintenance, and monitoring This should be regotiated with hibal governments - they (OMM) at the site? need to be involved. o get the debris out of landfills - not satisfied - theres still possibility for Things to migrate out. Its just grand. for a cap.

or Decision Document?
* Hetals taken it island to be very led have shown weeks wanter have decreased in the MILL.
* Scals numbers have decreased in the
arla.
* Determining Pol was tioquiec to was maccurate by without a reasonable doubt.
7. Are you aware of any changes in land use, access, or other site conditions that have occurred in the past five years that you feel may impact the protectiveness of the site? People are scared of the area. Peror to the cleanup there was high levels of PCB -
- Wash all of the berries - Wash all of the berries - Dist stirred up is a concern-did this result in spread of PCBS.
result in spread of the
8. Do you have any comments, suggestions, or recommendations regarding the site's management or operation? Most Imp.—It is allegal that the Wative Village,
management or operation? Most Imp.—It is illegal that their signed. The DD and excluded the Native Village. The DD and excluded the Strong opposition. We have strong of their interpret itself.
to the semedies and the accought to would like closure brought to Native Village would like the pay including Native Village
would like closure stong Native Village this cleaning by including Native Village this cleaning and have a Congressional hearing of Savoonga and meds vecocuition and in Washington. The island weeks vecocuition and in Washington. The island weeks vecocuition and in Washington. The island the peoples human for the yole they played for this country and for the peoples human.
1 - What to the live of the state of Miller
in warmany they played the some ces human

6. Have any problems been encountered which required, or will require, changes to the remedy

or Decision Document?

PCB as high as 7.5 ppm on the 181and.



Record of Decision Awald be Khatwe Village of Savoonga and the Commander and Chief not corps and State of At.

APPENDIX F Public Notice Documentation

US Army Corps of Engineers Announces Start of Five-Year Review

The Unites States Army Corps of Engineers at Joint Base Elmendorf-Richardson (JBER) announces the beginning of the Five-Year Review of cleanup remedies being implemented at the Northeast Cape Formerly Used Defense Site located on St. Lawrence Island, Alaska.

The Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Section 121, and the National Contingency Plan requires that remedial actions which result in any hazardous substances, pollutants, or contaminants remaining at the site above levels that allow for unlimited use and unrestricted exposure be subject to a five-year review.

The purpose of the Five-Year Review is to evaluate whether the remedies selected to clean up contaminated sites are operating as designed and remain protective of human health and the environment.

Detailed information concerning the Northeast Cape cleanup effort is available at the following information repositories:

Alaska Resources Library & Information Services, University of Alaska, Anchorage 3211 Providence Drive (907) 786-1871

> Savoonga City Hall (907) 984-6614

Gambell Sivuqaq Lodge (907) 985-5335

The findings of the Five-Year Review will be available for review after September 2014.

Interested persons can participate in the Five-Year Review process through December 2013 by responding to a questionnaire available from:

Kevin Maher, Jacobs Engineering 4300 B Street, Suite 600 Anchorage, AK 99508 kevin.maher@jacobs.com (907) 563-3322

Information on the cleanup process is shared with interested persons through periodic Northeast Cape public meetings. If you would like to be added to the contact list, contact Valerie Palmer at (907) 753-2578 or POA-FUDS@usace.army.mil

Publisher's Affidavit

UNITED STATES OF AMERICA,)
State Of Alaska	SS:
Second Division	
	, being first duly
	sworn on oath deposes and says:
	That I am and was at all times herein this affidavit mentioned
	administrator-ads
	of THE NOME NUGGET,
	newspaper of general circulation and published weekly a
	Nome, Second Division, State of Alaska, and online tha
	the Start of 5-42 traverse Islam
	a printed copy of which is hereto annexed, was published
	in said paper once and every week for
	successive and consecutive weeks in the issues of the following
	dates:
	august 22, 2019
	X N. C
	SUBSCRIBED and SWORN to before me this
	and day of Othober, 20 13
	NOTARY PUBLIC in and for the MCG State of Alaska.

FIVE-YEAR REVIEW NORTHEAST CAPE FORMERLY USED DEFENSE SITE ST. LAWRENCE ISLAND, ALASKA



September 2013

FIVE-YEAR REVIEW

The United States Army Corps of Engineers (USACE) at Joint Base Elmendorf-Richardson is undergoing a five-year review of remedial actions implemented at the Northeast Cape Formerly Used Defense Site located on St. Lawrence Island, Alaska.

The five-year review is a detailed evaluation of the implementation and performance of the remedy selected to achieve environmental cleanup. The objective of the evaluation is to document if cleanup activities (or "remedies") are protecting people and the environment. If the remedies are not effective, the five-year review makes recommendations to improve protectiveness. This evaluation is required by federal regulations, and the Alaska Department of Environmental Conservation (ADEC) will review the process to ensure completeness and accuracy. This will be the first five-year review for Northeast Cape.

SITES INCLUDED IN THE FIVE YEAR REVIEW

Based on the signed decision documents, remedial actions were selected for various sites to address surface soil, subsurface soil, groundwater, and sediment contaminated with polychlorinated biphenyls (PCB), diesel-range organics (DRO), residual-range organics (RRO), arsenic, benzene, and naphthalene. The following table lists the sites and the remedial actions performed at each site.

Site Number and Name		Action
Site 1	Air Strip	EX/D
Site 3	Fuel Pumphouse	EX/D
Site 6	Gravel Pad	EX/D
Site 7	Cargo Beach Road Landfill	C/LUC
Site 8	Petroleum, Oil, and Lubricant Spill	MNA/LUC
Site 9	Housing and Operations Landfill	C/LUC
Site 10	Buried Drums	EX/D and MNA/LUC ¹
Site 11	Fuel Tanks	EX/D and MNA/LUC ¹
Site 13	Heat and Power Plant	EX/D and MNA/LUC ¹

Site Number and Name		Action
Site 15	Fuel Pipeline	EX/D and MNA/LUC ¹
Site 16	Paint and Dope Storage	EX/D
Site 19	Auto Maintenance	EX/D and MNA/LUC ¹
Site 21	Wastewater Tank	EX/D
Site 27	Diesel Fuel Pump	EX/D and MNA/LUC ¹
Site 28	Drainage Basin	EX/D
Site 29	Suqitughneq River	Incidental Debris Removal
Site 31	White Alice Communications	EX/D
Site 32	Lower Tramway	EX/D

Notes:

EX/D = Excavation with disposal or treatment

MNA/LUC = Monitored natural attenuation with land use controls

C/LUC = Capping with land use controls

¹Although chemical oxidation was identified as the primary remedy in the decision documents, it was not implemented. The contingency remedy described in the decision documents, excavation of soil and monitored natural attenuation of groundwater, will be implemented.

COMMUNITY INVOLVEMENT

The community is encouraged to participate in the review process. Public comments may be provided by responding to a written questionnaire through December 2013, or in person following the December 2013 Restoration Advisory Board public meeting in Savoonga. The questionnaire can be requested from and comments submitted to:

ADDITIONAL INFORMATION

Documents pertaining to background information and the decision documents for Northeast Cape are on file at the following information repository locations:

Alaska Resources Library and Information Services, University of Alaska, Anchorage 3211 Providence Drive

(907) 786-1871

Savoonga City Hall (907) 984-6614

Gambell Sivuqaq Lodge

(907) 985-5335

Information on the cleanup process is shared with interested persons through periodic public meetings. If you would like to be added to the contact list, contact Valerie Palmer at (907) 753-2578 or POA-FUDS@usace.army.mil

US ARMY CORPS OF ENGINEERS

Alaska District P.O. Box 6898 (CEPOA-PM-ESP) JBER, AK 99506-0898

OFFICIAL BUSINESS

DELIVER TO: