



DEPARTMENT OF THE NAVY

ENGINEERING FIELD ACTIVITY, NORTHWEST
NAVAL FACILITIES ENGINEERING COMMAND
3505 NW ANDERSON HILL ROAD
SILVERDALE, WA 98383-9130

NCSDP 5.1
RECEIVED

JUN 18 1991

FEDERAL FACILITIES SF BR.

5090--ST LAW ISL
09ERI4/3459
14 June 1991

RECEIVED

JUN 20 1991

SUPERFUND BRANCH

Jim Everts
~~Mr. George Hofer
Head, Federal Facilities Branch
U. S. Environmental Protection Agency
1200 Sixth Avenue, HW-074
Seattle, WA 98181~~

Dear Mr. Hofer,

Enclosed is a copy of the final Site Inspection Report for the Navy property at Northeast Cape, Saint Lawrence Island for your information.

Some of the analytical data used in this report is unvalidated due to problems with one of the analytical laboratories. We have tasked our contractor with resampling the transformer pads and the areas around them to obtain validated data on these areas. They anticipate visiting the Northeast Cape site later this summer to obtain samples and we will then revise the Site Inspection Report using the new data.

Our point of contact is Mr. Douglas Thelin at (206) 476-5775.

Sincerely

Kevin Stigile

Kevin W. Stigile
By direction of the
Commanding Officer

Encl:
(Site Inspection, White Alice
Site, Northeast Cape, St. Lawrence Island, AK)

Copy to:
EPA Alaska Ops Off. (M. Coomes)

*Marcia Coombs
a copy also got*

USEPA SF



1477077